



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Black
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-23
Pictures	23
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #17</b>	2023-04-04 14:09
<b>MOT test number</b>	955693924523
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-04-03
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #16</b>	2023-04-04 09:54
<b>MOT test number</b>	473924444786
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Fail</b>	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

<b>MOT #15</b>	2022-03-18 11:37
<b>MOT test number</b>	399549943416
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Shock absorber cover insecure
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14**

2022-03-18 10:18

**MOT test number**

832256267047

**Result**

✗ Failed

- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
  - Advice** Offside Rear handbrake cable disconnected
  - Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Rear Brake lever has restricted free movement Handbrake lever on calliper seized (1.1.15 (e))
  - Advice** Nearside Rear Shock absorber cover insecure
  - Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #13**

2021-03-30 13:51

**MOT test number**

448627659799

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2020-03-27 14:05

**MOT test number**

152955011050

**Result**

✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Offside Rear Slight bind

**MOT #11**

2019-03-25 16:11

**MOT test number**

504833598179

**Result**

✓ Passed

**MOT #10** 2019-03-25 08:59**MOT test number** 170009468319**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #9** 2018-03-27 08:49**MOT test number** 294427481126**Result** ✓ Passed**MOT #8** 2017-03-03 11:39**MOT test number** 297076171532**Result** ✓ Passed**Advice** Both rear coil springs poor condition**Advice** Front console bushes lower arm rear starting to age crack**Advice** Washer aim poor, low on screen**MOT #7** 2016-02-26 14:31**MOT test number** 300139418313**Result** ✓ Passed**MOT #6** 2015-03-04 10:45**MOT test number** 685533065043**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-04-15 12:38**MOT test number** 295785304478**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-05-17 10:10**MOT test number** 226637233194**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-06-08 13:59**MOT test number** 109790762179**Result** ✓ Passed**MOT #2** 2011-06-11 11:42**MOT test number** 825672661168**Result** ✓ Passed**MOT #1** 2011-06-10 11:40**MOT test number** 407571961114**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AM08WFP</b>
Plate since	2024-03-29
Current registration	 <b>AM08WFP</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-27
Last registration	2023-04-04
Complete history	<a href="#">See info</a>



Registration #1	2008-03-27	14 mi
Registration #2	2011-06-10	19.396 mi
Registration #3	2011-06-11	19.396 mi
Registration #4	2012-06-08	28.934 mi
Registration #5	2013-05-17	36.698 mi
Registration #6	2014-04-15	45.406 mi
Registration #7	2015-03-04	49.073 mi
Registration #8	2016-02-26	54.898 mi
Registration #9	2017-03-03	61.211 mi
Registration #10	2018-03-27	68.219 mi
Registration #11	2019-03-27	75.227 mi
Registration #12	2020-03-27	82.235 mi
Registration #13	2021-03-27	89.243 mi
Registration #14	2022-03-27	96.251 mi
Registration #15	2023-03-27	103.259 mi
Registration #16	2024-03-27	110.267 mi
Registration #17	2025-03-27	117.275 mi
Registration #18	2026-03-27	124.283 mi
Registration #19	2027-03-27	131.291 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1548 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BMM 208282