



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Black
Year of manufacture	2016
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-17
Pictures	19
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-16
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-07-31
<b>MOT pass rate</b>	63 %
<b>MOT passed</b>	5
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	8
<b>Total items failed</b>	7

<b>MOT #8</b>	2023-07-11 14:33
<b>MOT test number</b>	714887776744
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-07-31
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt

<b>MOT #7</b>	2023-07-11 08:13
<b>MOT test number</b>	809836504012
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
<b>Fail</b>	Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
<b>Fail</b>	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2022-07-26 07:58**MOT test number** 727110522436**Result** ✓ Passed**Advice** Front exhaust flexi deteriorated - no major leaks**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside front tyre wall scuffed**MOT #5** 2022-07-26 07:58**MOT test number** 401515138482**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front exhaust flexi deteriorated - no major leaks**Advice** Offside front tyre wall scuffed**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #4** 2021-07-08 14:23**MOT test number** 331452493406**Result** ✓ Passed**MOT #3** 2020-07-16 11:32**MOT test number** 195237439478**Result** ✓ Passed**MOT #2** 2019-07-31 15:49**MOT test number** 341869264586**Result** ✓ Passed



MOT #1	2019-07-30 14:10
MOT test number	450817169379
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
31 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	31 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-08-01
Last registration	2023-07-11
Complete history	<a href="#">See info</a>



Registration #1	2016-08-01	19 mi
Registration #2	2019-07-30	22.093 mi
Registration #3	2019-07-31	22.095 mi
Registration #4	2020-07-16	32.341 mi
Registration #5	2021-07-08	43.105 mi
Registration #6	2022-07-08	54.869 mi
Registration #7	2022-07-09	54.877 mi
Registration #8	2022-07-10	54.885 mi
Registration #9	2022-07-11	54.893 mi
Registration #10	2022-07-12	54.901 mi
Registration #11	2023-07-11	54.909 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19MG7042LDD