



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI DSG
Colour	Silver
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2021-07-02
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	19
Total items failed	8

MOT #11	2020-06-24 16:37
MOT test number	613441979543
Result	✓ Passed
Next expiry date	2021-07-02

MOT #10	2019-06-26 14:29
MOT test number	476175971104
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2018-07-03 17:15
MOT test number	241922657019
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8**

2017-10-09 13:30

MOT test number

635332653824

Result

✓ Passed

- Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Oil leak
- Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)

MOT #7

2017-09-29 14:39

MOT test number

350310557137

Result

✗ Failed

- Fail** Battery insecure (1.9.1)
- Fail** Offside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Oil leak
- Fail** Offside Front Inner Tyre has ply or cords exposed 235/45r17 budget range extra load (4.1.D.1b)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #6** 2016-09-27 14:40**MOT test number** 634126003195**Result** ✓ Passed**MOT #5** 2014-06-10 14:20**MOT test number** 795561964149**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-03-13 12:03**MOT test number** 958062673044**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-03-01 15:46**MOT test number** 579321262036**Result** ✓ Passed

- Notice** Nearside rear parking brake low effort, possibly incorrectly adjusted

MOT #2 2011-02-14 14:48**MOT test number** 986035441053**Result** ✓ Passed**MOT #1** 2010-03-02 11:10**MOT test number** 112141660439**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
10 December 2020

✕
MOT

Expired:
2 July 2021

Tax status	Expired at 10 December 2020
Days left	1236 days too late
MOT expiry date	2 July 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WV07UYK
Plate since	2019-06-29
Current registration	WV07UYK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2007-03-10
Last registration	2020-06-24
Complete history	See info



Registration #1	2007-03-10	8 mi
Registration #2	2010-03-02	27.945 mi
Registration #3	2011-02-14	39.723 mi
Registration #4	2012-03-01	49.703 mi
Registration #5	2013-03-13	60.718 mi
Registration #6	2014-06-10	73.310 mi
Registration #7	2015-06-20	85.377 mi
Registration #8	2016-06-20	95.377 mi
Registration #9	2017-06-20	105.377 mi
Registration #10	2018-06-20	115.377 mi
Registration #11	2019-06-20	125.377 mi
Registration #12	2020-06-24	135.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1574 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BMM 113408