



HYUNDAI



report date: 2024-03-29

General information

| | |
|---------------------|-------------------------------|
| Make | HYUNDAI |
| Model | TUCSON CRDI SE NAV BLUE DRIVE |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 109 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 280 Nm at 1.250 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |






Internet history

Entry 5

| | |
|---------------|-----------------------------|
| Date | 2021-12-24 |
| Pictures | 35 |
| Listing price | View report |



source: autotrader.co.uk


Entry 4

| | |
|---------------|-----------------------------|
| Date | 2021-12-24 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2021-10-23 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 2




| | |
|---------------|-----------------------------|
| Date | 2021-10-23 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

Entry 1

CarCheck.co.uk

| | |
|---------------|-----------------------------|
| Date | 2021-10-22 |
| Pictures | 12 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-21 |
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 11 |
| Total items failed | 0 |

MOT #4 2023-10-13 17:09

MOT test number 658532124031

Result ✓ Passed

Next expiry date 2024-10-21

- Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Parking brake lever has high travel but still has reserve
- Advice** Front Brake pad(s) wearing thin nearside and offside[on the limit] (1.1.13 (a) (ii))
- Advice** Rear Outer Tyre worn close to legal limit/worn on edge outer band wearing quicker than rest of tyres[nearside and offside] (5.2.3 (e))

MOT #3 2022-10-12 13:58

MOT test number 888605481688

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2021-10-22 14:58

MOT test number 890875952672

Result ✓ Passed



MOT #12021-06-09 08:50

MOT test number111895307344

| Result | | ✓ Passed |
|--------|--|----------|
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Minor | Rear Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
21 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 21 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AK18ZWR |
| Plate since | 2019-03-29 |
| Current registration | AK18ZWR |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2018-07-02 |
| Last registration | 2023-10-13 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2018-07-02 | 9 mi |
| Registration #2 | 2021-06-09 | 30.127 mi |
| Registration #3 | 2021-10-22 | 34.508 mi |
| Registration #4 | 2022-05-20 | 35.277 mi |
| Registration #5 | 2022-05-20 | 35.277 mi |
| Registration #6 | 2022-05-20 | 35.277 mi |
| Registration #7 | 2022-05-20 | 35.277 mi |
| Registration #8 | 2022-05-20 | 35.277 mi |
| Registration #9 | 2022-05-20 | 35.277 mi |
| Registration #10 | 2022-05-20 | 35.277 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1850 mm |
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1580 kg |
| Max. allowed weight | 2000 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|--------------|
| Number of axles | 2 |
| Engine number | D4FDHZ758691 |