





report date: 2024-03-28

General information

Make	HONDA
Model	S2000 16V
Colour	Blue
Year of manufacture	2009
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	236 BHP
Max. torque	204 Nm at 6.500 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.2 mpg
CO2 emission	236 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-21


Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



AV09FCZ report date: 2024-03-28

MOT history

MOT expiry date	2025-04-12
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #14		2024-04-05 09:50
MOT test	number	140967625017
Result		✓ Passed
Next expi	ry date	2025-04-12
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing Cracking around	outer edge (5.2.3 (d)

MOT #13	2023-04-13 12:11
MOT test number	708825582177
Result	✓ Passed
MOT #12	2022-02-18 15:12
MOT test number	360935358033
Result	✓ Passed
MOT #11	2021-03-02 14:34
MOT test number	939491281453
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10	2019-11-21 13:03
MOT test number	981956415578
Result	✓ Passed
MOT #9	2018-11-08 10:39
MOT test number	793007045447
Result	✓ Passed
MOT #8	2017-11-02 09:03
MOT #8 MOT test number	2017-11-02 09:03 265850426882
MOT test number	265850426882
MOT test number Result	265850426882

MOT #7	2017-11-01 10:31
MOT test number	611227827226
Result	X Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Play in steering rack inner joint(s)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Rear Anti-roll bar linkage insecure (2.4.G.1)	

MOT #6	2016-11-28 12:02
MOT test number	336159077261
Result	✓ Passed
Advice Front suspension bushes starting to debond	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2016-01-28 12:19

MOT test number 458091190243

Result
✓ Passed

MOT #4 2015-02-19 11:23

MOT test number 127920355453

Result

Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

MOT #3 2014-02-12 10:55

MOT test number 399943544048

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-02-22 14:20

MOT test number 966173753089

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-03-02 16:31

MOT test number 135082862472

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

e when history	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



AV09FCZ report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-06
Last registration	2024-04-05
Complete history	See info



Registration #1	2009-03-06	20 mi
Registration #2	2012-03-02	33.681 mi
Registration #3	2013-02-22	42.765 mi
Registration #4	2014-02-12	51.179 mi
Registration #5	2015-02-19	63.407 mi
Registration #6	2016-01-28	63.817 mi
Registration #7	2016-11-28	64.089 mi
Registration #8	2017-11-01	74.539 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		0.074
Registration #16		71.777 es

More info >

CarCheck.co.uk page 11/12



AV09FCZ report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width 1750 mm
1005
Height 1285 mm
Length 4135 mm
Max. allowed weight 1535 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	NOTKNOWN

CarCheck.co.uk page 12/12