





report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Black
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2020-03-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	24
Total items failed	9

MOT #15	2019-03-16 11:02	
MOT test number	935529734757	
Result	✓ Passed	
Next expiry date	2020-03-15	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Front Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))		
Advice Offside Front Headlamp has a product on the lens but not seriously reducing lig (b))	ght output (4.1.4	

MOT #14	2019-03-07 14:21	
MOT test number	390747863450	
Result	× Failed	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Front Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Fail Offside Front Suspension rod pin or bush excessively worn (5.3.4 (a) (i))		
Advice Offside Front Headlamp has a product on the lens but not seriously reducing (b))	ng light output (4.1.4	

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #13 2019-01-07 12:49

MOT test number 792972098414

Result X Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush / front lower arm (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction engine warning lamp illuminated (8.2.1.2 (h))

Minor Offside Front Headlamp lens slightly defective outer lens weathering (4.1.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2018-01-02 14:10

MOT test number 547142177062

Result \(\sqrt{Passed} \)

Advice Front Inner Brake pad(s) wearing thin nearside on limit (3.5.1g)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #11 2017-12-28 13:34

MOT test number 724061298603

Result × Failed

Advice Front Inner Brake pad(s) wearing thin nearside on limit (3.5.1g)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Fail Nearside Headlamp aim too far to the right unable to adjust (1.8)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush - marked in yellow (2.4.G.2)

Fail Offside Rear coil spring broken (2.4.C.1a)

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #10 2016-12-16 14:17

MOT test number 576897162650

Result ✓ Passed

MOT #9 2016-12-15 10:59

MOT test number 374781404488

Result X Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #8 2015-11-28 13:09

MOT test number 547571050246

Result
✓ Passed

Advice Child seats fitted too n/s/r & o/s/r seats

seats

MOT #7 2014-12-18 12:44

MOT test number 839822354383

Notice Child seat fitted not allowing full inspection of adult belt , fitted too near side and off side rear

Notice Vehicle's internal headlight adjuster altered to recheck lights

MOT #6 2014-12-18 12:44

MOT test number 976882254364

Result X Failed

Notice Child seat fitted not allowing full inspection of adult belt , fitted too near side and off side rear seats

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Vehicle's internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #5

MOT test number

Result

Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)

MOT #4

MOT test number

Result

Notice UNABLE TO FULLY INSPECT NEAR SIDE REAR SEAT BELT DUE TO CHILD SEAT FITTED

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

807940801335

Result

✓ Passed

MOT #2

2010-10-27 12:41

MOT test number 751480300354
Result ✓ Passed

 MOT #1
 2009-11-10 17:40

 MOT test number
 172164119370

 Result
 ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union motory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-10-28
Last registration	2019-03-16
Complete history	See info



Registration #1	2006-10-28	7 mi
Registration #2	2009-11-10	6.337 mi
Registration #3	2010-10-27	16.321 mi
Registration #4	2011-10-27	25.868 mi
Registration #5	2012-12-01	36.011 mi
Registration #6	2013-12-17	45.176 mi
Registration #7	2014-12-18	54.570 mi
Registration #8	2015-11-28	64.210 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,709 esi
Registration #12		11.777 es
Registration #13		91,709 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11