



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Blue
Year of manufacture	2001
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-12
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-07
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	35
Total items failed	8

MOT #22	2024-04-05 13:39
MOT test number	563187126065
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #21	2023-04-08 08:49
MOT test number	464572056786
Result	✓ Passed
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20	2022-03-17 16:38
MOT test number	594693412665
Result	✓ Passed

MOT #19	2021-03-01 09:01
MOT test number	199146746122
Result	✓ Passed

**MOT #18**

2021-01-06 09:28

**MOT test number**

184737478001

**Result**

✗ Failed

**Fail**

Offside Seat belt anchorage prescribed area strength or continuity significantly reduced Lower door pillar (7.1.1 (a) (i))

**Fail**

Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #17**

2019-07-08 15:52

**MOT test number**

227007649001

**Result**

✓ Passed

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

General corrosion on front and rear suspension

**Advice**

Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #16**

2018-07-09 16:10

**MOT test number**

373754362846

**Result**

✓ Passed

**Advice**

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice**

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Minor**

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice**

Rear Floor, chassis and inner sill areas corroded

**Advice**

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2018-07-04 12:19

**MOT test number**

851390017240

**Result****✗ Failed****Minor**

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice**

Rear Floor, chassis and inner sill areas corroded

**Fail**

Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**Advice**

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice**

Parking brake lever has little reserve travel

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge Worn on both edges (5.2.3 (e))

**Fail**

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**Advice**

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2017-07-03 08:54

**MOT test number**

876515728919

**Result****✓ Passed****Advice**

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice**

Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #13**

2016-07-06 13:52

**MOT test number**

173307176133

**Result**

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Rear suspension corroded
- Advice** Offside Front Valve stem slightly damaged (4.1.D.1e)
- Advice** Front suspension corroded
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Exhaust heat shield insecure

**MOT #12**

2015-07-08 13:00

**MOT test number**

839629585186

**Result**

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Advice** Rear Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #11**

2014-02-19 14:48

**MOT test number**

148120454065

**Result**

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2013-02-12 10:02**MOT test number** 545573143087**Result** ✓ Passed**Notice** O/s wiper starting to split.**MOT #9** 2012-02-15 09:55**MOT test number** 728006042074**Result** ✓ Passed**MOT #8** 2011-02-17 16:47**MOT test number** 658958241037**Result** ✓ Passed**MOT #7** 2010-08-17 12:16**MOT test number** 881539520267**Result** ✓ Passed**MOT #6** 2010-08-17 12:16**MOT test number** 753429120265**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2009-08-27 11:54**MOT test number** 421689039231**Result** ✓ Passed**MOT #4** 2008-08-29 12:06**MOT test number** 270862548255**Result** ✓ Passed



MOT #3	2007-08-29 13:12
MOT test number	610631947216
Result	✓ Passed

MOT #2	2007-08-29 10:57
MOT test number	303421747418
Result	✗ Failed
<div><div>Fail</div>Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	
<div><div>Fail</div>Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	

MOT #1	2006-12-04 16:00
MOT test number	670388436339
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>CN51CXK</b>
Plate since	2024-03-28
Current registration	<b>CN51CXK</b>
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2001-09-13
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2001-09-13	23 mi
Registration #2	2006-12-04	51.894 mi
Registration #3	2007-08-29	52.002 mi
Registration #4	2007-08-29	52.002 mi
Registration #5	2008-08-29	63.567 mi
Registration #6	2009-08-27	72.938 mi
Registration #7	2010-08-17	80.800 mi
Registration #8	2011-02-17	81.695 mi
Registration #9	2012-02-15	88.655 mi
Registration #10	2013-02-12	92.396 mi
Registration #11	2014-02-19	96.165 mi
Registration #12	2015-07-08	101.633 mi
Registration #13	2016-06-20	101.633 mi
Registration #14	2016-06-20	101.633 mi
Registration #15	2016-06-20	101.633 mi
Registration #16	2016-06-20	101.633 mi
Registration #17	2016-06-20	101.633 mi
Registration #18	2016-06-20	101.633 mi
Registration #19	2016-06-20	101.633 mi
Registration #20	2016-06-20	101.633 mi
Registration #21	2016-06-20	101.633 mi
Registration #22	2016-06-20	101.633 mi
Registration #23	2016-06-20	101.633 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0771609