





General information

| Make | MAZDA |
|---------------------|-------------------|
| Model | 5 VENTURE EDITION |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 120 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 191 Nm at 4.500 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |







Internet history


| Entry 1 | | | |
|---------|---|--|--|
| Date | | | |
| Picture | s | | |

2021-07-27

32

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-26 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #11 | 2023-08-09 12:45 |
|------------------|------------------|
| MOT test number | 907859884778 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-26 |

| MOT #10 | | 2023-08-09 10:03 |
|---------------|--|------------------|
| MOT test nu | mber | 237409810987 |
| Result | | 🗙 Failed |
| MAJOR E | ngine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Advice | Central exhaust heat sheild loose | |
| DANGERO | JS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| DANGERO | JS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

| МОТ #9 | 2022-08-26 10:47 |
|-----------------|------------------|
| MOT test number | 692654808495 |
| Result | ✓ Passed |

| MOT #8 | 2021-08-27 12:17 |
|-----------------|------------------|
| MOT test number | 700927841781 |
| Result | ✓ Passed |





| MOT #7 | 2021-01-20 09:07 |
|--|------------------|
| MOT test number | 414912056147 |
| Result | ✓ Passed |
| | |
| МОТ #6 | 2020-02-03 13:33 |
| MOT test number | 122187441299 |
| Result | Passed |
| | |
| MOT #5 | 2019-02-14 12:59 |
| MOT test number | 715627700539 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2018-02-15 15:37 |
| MOT test number | 602333774102 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2018-02-15 13:56 |
| MOT test number | 720095457166 |
| Result | 🗙 Failed |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| | |
| MOT #2 | 2017-02-17 16:33 |
| MOT test number | 649825734734 |

MOT test number649825734734ResultPassed

| MOT #1 | 2016-03-11 16:42 |
|-----------------|------------------|
| MOT test number | 374613116460 |
| Result | ✓ Passed |



Tax & MOT check

| Taxed Tax due: 1 September 2024 | MOT Expires: 26 August 2024 |
|---|---|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 26 August 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | 4. ARANPE |
| Туре | |
| Damage 2 | AMPL |
| Damage 2 | E CUT-S |
| Date | * |
| Category | AMP |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-03-27 |
| Last registration | 2023-08-09 |
| Complete history | See info |



| Registration #1 | 2013-03-27 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2016-03-11 | 22.548 mi |
| Registration #3 | 2017-02-17 | 27.926 mi |
| Registration #4 | 2018-02-15 | 33.056 mi |
| Registration #5 | 2018-02-15 | 33.056 mi |
| Registration #6 | 2019-02-14 | 38.046 mi |
| Registration #7 | 2020-02-03 | 42.399 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 mi |





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|-----------------------|
| Width | 1988 mm |
| Height | 1615 mm |
| Length | 4585 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1485 kg |
| Max. allowed weight | 2125 kg |
| Additional information | |
| Fuel tank capacity | 60 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Engine number | LF 11502460 |