



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D S
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-04-06
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-13
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-09-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	27
Total items failed	6

MOT #16 2023-09-09 09:32

MOT test number 705717654341

Result ✓ Passed

Next expiry date 2024-09-22

Advice Front Inner Tyre worn close to legal limit/worn on edge both front inner tyres wearing (5.2.3 (e))

Advice Rear Inner Tyre worn close to legal limit/worn on edge both rear inner tyre dangerously close to cords! (5.2.3 (e))

MOT #15 2022-09-01 09:05

MOT test number 993650508133

Result ✓ Passed

MOT #14 2021-09-23 11:35

MOT test number 330402816371

Result ✓ Passed

Advice Engine covers & under trays fitted obscuring view of some components

MOT #13 2020-03-23 10:10

MOT test number 472182100607

Result ✓ Passed

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2019-03-25 12:44**MOT test number** 454887447490**Result** ✓ Passed**MOT #11** 2019-03-25 09:17**MOT test number** 262662087603**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2018-03-22 08:46**MOT test number** 131037362875**Result** ✓ Passed**Advice** Nearside Rear tyre mishaped**MOT #9** 2018-03-20 18:27**MOT test number** 226495198468**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)**Advice** Nearside Rear tyre mishaped**MOT #8** 2017-03-24 08:54**MOT test number** 272026884557**Result** ✓ Passed

**MOT #7**

2016-03-29 07:57

MOT test number

712446841689

Result

✓ Passed

- Advice** Under tray fitted obscuring some components
- Advice** Front brake pads getting low
- Advice** Engine cover fitted obscuring some components
- Advice** Front brake discs worn
- Advice** N/s/f tyre tread getting low

MOT #6

2015-03-20 16:05

MOT test number

928639175042

Result

✓ Passed

MOT #5

2015-03-20 08:43

MOT test number

768959075008

Result

✗ Failed

- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #4

2014-03-24 15:55

MOT test number

777473184062

Result

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seat fitted to n/s/r
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2014-03-24 12:48**MOT test number** 138733284450**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted to n/s/r**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Parking brake lever has no reserve travel (3.1.6b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-03-28 13:13**MOT test number** 478307783056**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front tyre treads getting low**Notice** Child seat fitted to n/s/r**MOT #1** 2013-03-28 09:35**MOT test number** 758677783024**Result** ✗ Failed**Notice** Child seat fitted to n/s/r**Fail** Parking brake lever has no reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front tyre treads getting low



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	HN59EAY
Plate since	2019-03-28
Current registration	HN59EAY
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-02-02
Last registration	2023-09-09
Complete history	See info



Registration #1	2010-02-02	16 mi
Registration #2	2013-03-28	34.757 mi
Registration #3	2013-03-28	34.758 mi
Registration #4	2014-03-24	41.305 mi
Registration #5	2014-03-24	41.306 mi
Registration #6	2015-03-20	47.346 mi
Registration #7	2015-03-20	47.346 mi
Registration #8	2016-03-29	53.773 mi
Registration #9	2017-03-24	57.233 mi
Registration #10	2018-03-20	60.784 mi
Registration #11	2019-03-20	65.233 mi
Registration #12	2019-03-20	65.233 mi
Registration #13	2019-03-20	65.233 mi
Registration #14	2019-03-20	65.233 mi
Registration #15	2019-03-20	65.233 mi
Registration #16	2019-03-20	65.233 mi
Registration #17	2019-03-20	65.233 mi
Registration #18	2019-03-20	65.233 mi
Registration #19	2019-03-20	65.233 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	727050
---------------	--------