



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V E4
Colour	Red
Year of manufacture	2007
Top speed	101 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	94 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-15
Pictures	22
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-20
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	39
Total items failed	19

MOT #22	2024-02-16 12:02
MOT test number	452756324741
Result	✓ Passed
Next expiry date	2025-02-20
Minor	Rear Fuel pipe chafing To tank (6.1.3 (c) (i))

MOT #21	2023-02-21 15:06
MOT test number	454223563084
Result	✓ Passed

MOT #20	2023-02-10 17:54
MOT test number	463096007029
Result	✗ Failed
Fail	Rear fog lamp does not emit a steady red light (4.5.4 (a))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	NSF Fog lamp not working
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #19** 2022-02-12 10:30**MOT test number** 396700718340**Result** ✓ Passed**MOT #18** 2022-02-12 10:30**MOT test number** 847656398163**Result** ✗ Failed**Pass with rectification** Nearside Front Service brake excessively binding (1.2.1 (f))**MOT #17** 2021-10-14 15:52**MOT test number** 513549875838**Result** ✓ Passed**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #16** 2020-10-26 17:13**MOT test number** 271143515678**Result** ✓ Passed

**MOT #15**

2020-10-26 11:08

**MOT test number**

754858101928

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Rear Brakes imbalanced across an axle bind at n/s/r (1.2.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Emissions not tested exhaust leak (8.2.1.2 (d))
- Advice** Offside Front Play in steering rack inner joint(s)

**MOT #14**

2019-11-14 09:39

**MOT test number**

533882324428

**Result****✗ Failed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn on inner edge
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2018-11-27 13:25

**MOT test number**

734049607080

**Result**

✓ Passed

- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Steering arm deformed but serviceable slight play in both sides (2.1.3 (c) (i))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #12**

2018-11-27 12:38

**MOT test number**

437376756129

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Steering arm deformed but serviceable slight play in both sides (2.1.3 (c) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2017-11-08 12:41**MOT test number** 129880421755**Result** ✓ Passed**Advice** Nearside Front fog light not working**MOT #10** 2017-11-06 13:30**MOT test number** 384336739857**Result** ✗ Failed**Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front fog light not working**MOT #9** 2016-09-23 08:02**MOT test number** 924282770748**Result** ✓ Passed**MOT #8** 2015-09-25 09:21**MOT test number** 921186716672**Result** ✓ Passed**MOT #7** 2015-09-25 09:21**MOT test number** 319078649038**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too far to the left (1.8)**Pass with rectification** Nearside Headlamp aim too far to the left (1.8)**MOT #6** 2014-10-14 11:26**MOT test number** 426827284218**Result** ✓ Passed

**MOT #5** 2013-10-17 15:29**MOT test number** 369280693406**Result** ✓ Passed**MOT #4** 2012-02-17 11:24**MOT test number** 718078042016**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2012-02-16 14:41**MOT test number** 199047842015**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-04-04 14:41**MOT test number** 846154991027**Result** ✓ Passed**Notice** Front brake disks heavily corroded**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-05-17 13:02**MOT test number** 923897430180**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	20 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-06-18
Last registration	2024-02-16
Complete history	<a href="#">See info</a>



Registration #1	2007-06-18	12 mi
Registration #2	2010-05-17	9.086 mi
Registration #3	2011-04-04	14.472 mi
Registration #4	2012-02-16	20.628 mi
Registration #5	2012-02-17	20.628 mi
Registration #6	2013-10-17	24.980 mi
Registration #7	2014-10-14	26.826 mi
Registration #8	2015-09-25	30.504 mi
Registration #9	2015-09-25	30.504 mi
Registration #10	2016-09-23	35.438 mi
Registration #11	2017-11-06	39.876 mi
Registration #12	2017-11-08	39.876 mi
Registration #13	2018-05-20	45.212 mi
Registration #14	2018-05-20	45.212 mi
Registration #15	2018-05-20	45.212 mi
Registration #16	2018-05-20	45.212 mi
Registration #17	2018-05-20	45.212 mi
Registration #18	2018-05-20	45.212 mi
Registration #19	2018-05-20	45.212 mi
Registration #20	2018-05-20	45.212 mi
Registration #21	2018-05-20	45.212 mi
Registration #22	2018-05-20	45.212 mi
Registration #23	2018-05-20	45.212 mi
Registration #24	2018-05-20	45.212 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2031 mm
Height	1825 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D016420