





report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Red
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



# Internet history

## Entry 1

Date 2021-08-05

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



	~		
10/1/	<b>1</b>	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-09-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #8	2023-09-13 15:28
MOT test number	833108688496
Result	✓ Passed
Next expiry date	2024-09-12

MOT #7		2022-07-26 10:50
MOT test	number	116993178630
Result		✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

NOT "C	2021.00.04.07.25
MOT #6	2021-08-04 07:35
MOT test number	741960305647
Result	✓ Passed
MOT #5	2020-10-20 15:37
MOT test number	525232961269
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

SX15JTY report date: 2024-03-28

Passed

MOT #4 2020-10-16 13:15

MOT test number 104124772224

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #3 2019-05-27 11:31

MOT test number 673547511346

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))

MOT #2 2019-05-27 11:31

MOT test number 64335133131

Result X Failed

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm. (5.2.3 (e))

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #1 2018-06-01 10:48

**MOT test number** 692213856594

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11




### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
*********	
***************************************	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 8/11



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-08-31
Last registration	2023-09-13
Complete history	See info



Registration #1	2015-08-31	9 mi
Registration #2	2018-06-01	6.284 mi
Registration #3	2019-05-27	13.348 mi
Registration #4	2019-05-27	13.348 mi
Registration #5	2020-10-16	22.593 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.00 m
•		1.77 m
Registration #7		1.77 m 1.77 m 1.77 m

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CHYA451626