



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Orange
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-05-21
Pictures	39
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	15
Total items failed	1

MOT #11	2024-04-12 10:40
MOT test number	134407826308
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Advise p a s light flashing intermittently

MOT #10	2024-04-12 10:40
MOT test number	390363171977
Result	✗ Failed
Advice	Advise p a s light flashing intermittently
Pass with rectification	Battery insecure and likely to fall from carrier (4.13 (a) (ii))

MOT #9	2023-04-17 13:00
MOT test number	594803722763
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on outer tread band (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on outer tread band recommend replacement (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil recommend replacement advise shock absorbers generally fitted as pairs (5.3.2 (b))

**MOT #8** 2022-04-21 16:41**MOT test number** 442088360340**Result** ✓ Passed**MOT #7** 2021-05-19 11:28**MOT test number** 147081755606**Result** ✓ Passed**MOT #6** 2021-05-18 15:51**MOT test number** 782837286652**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2020-10-30 12:34**MOT test number** 835582663600**Result** ✓ Passed**Advice** Oil leak, but not excessive CRANK SHAFT (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-10-02 11:45**MOT test number** 769531183119**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Windscreen wiper blade defective Both (3.4 (b) (i))



MOT #3	2018-10-24 09:06
MOT test number	886593126949
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #2	2017-10-25 10:36
MOT test number	886050966028
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #1	2016-10-19 14:18
MOT test number	405321478138
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-30
Last registration	2024-04-12
Complete history	See info



Registration #1	2013-10-30	20 mi
Registration #2	2016-10-19	66.822 mi
Registration #3	2017-10-25	87.675 mi
Registration #4	2018-10-24	111.966 mi
Registration #5	2019-10-02	131.605 mi
Registration #6	2020-10-30	142.156 mi
Registration #7	2021-05-18	143.706 mi
Registration #8	2022-05-20	151.277 mi
Registration #9	2023-05-20	151.277 mi
Registration #10	2023-05-20	151.277 mi
Registration #11	2023-05-20	151.277 mi
Registration #12	2023-05-20	151.277 mi
Registration #13	2024-04-12	151.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1680 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBDU824233