



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | MAZDA |
| Model | 6 D SE-L NAV |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 125 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 380 Nm at 1.800 rpm |
| Engine capacity | 2.191 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-23 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-26 |
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 14 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #7 | 2023-09-15 10:02 |
| MOT test number | 165460852113 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-26 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (1.1.14 (a) (ii)) |
| Advice | Rear Lower Suspension arm corroded but not seriously weakened Nearside & Offside (5.3.3 (b) (i)) |
| Advice | Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Nearside & Offside Rear Bushes (5.3.4 (a) (i)) |
| Advice | Rear Anti-roll bar linkage corroded but not seriously weakened Nearside & Offside (5.3.3 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #6 | 2022-09-27 16:01 |
| MOT test number | 813075989684 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2021-11-03 15:47 |
| MOT test number | 789976409812 |
| Result | ✓ Passed |

**MOT #4** 2020-09-10 10:11**MOT test number** 895783955111**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-09-10 08:42**MOT test number** 584046402982**Result** ✗ Failed

- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-09-20 13:44**MOT test number** 452768038551**Result** ✓ Passed**MOT #1** 2018-09-11 13:41**MOT test number** 212571349015**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
26 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 26 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | SR65EMX |
| Plate since | 2019-03-29 |
| Current registration | SR65EMX |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2015-09-23 |
| Last registration | 2023-09-15 |
| Complete history | See info |



| | | |
|-----------------|------------|------------|
| Registration #1 | 2015-09-23 | 18 mi |
| Registration #2 | 2018-09-11 | 89.442 mi |
| Registration #3 | 2019-09-20 | 103.580 mi |
| Registration #4 | 2020-09-10 | 114.814 mi |
| Registration #5 | 2020-09-10 | 114.814 mi |
| Registration #6 | 2020-09-20 | 114.814 mi |
| Registration #7 | 2020-09-20 | 114.814 mi |
| Registration #8 | 2020-09-20 | 114.814 mi |
| Registration #9 | 2020-09-20 | 114.814 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 93% |
| Children | 86% |
| Pedestrian | 65% |
| Safety systems | 81% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1795 mm |
| Height | 1465 mm |
| Length | 4465 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1330 kg |
| Max. allowed weight | 1930 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 51 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | SH 30543817 |