





report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 2 ISG
Colour	White
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	280 Nm at 3.000 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date	2021-09-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-08-31
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MD17XFN report date: 2024-03-28

MOT history

MOT expiry date	2025-01-11
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #6		2023-12-18 16:02
MOT test	number	271330470371
Result		✓ Passed
Next expi	ry date	2025-01-11
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or co	rds (5.2.3 (d) (i))
Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Minor	Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2023-12-18 15:25

MOT test number 719366869647

Result X Failed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

MOT #4 2023-01-09 11:40

MOT test number 833361288121

Result \rightarrow Passed

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush bonding failing (5.3.4 (a) (i))

Advice Nearside Front steering rack gaiter twisted

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush bonding failing (5.3.4 (a) (i))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #3 2022-01-12 10:55

MOT test number 799147879153

Result

Passed

MOT #2 2021-08-11 13:14

MOT test number 589207989575

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2020-08-06 08:00

MOT test number 325980118920

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
D	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

MD17XFN

report date: 2024-03-28

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this KIA had different number plates.

See in this check if this NA had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-08-07
Last registration	2023-12-18
Complete history	See info



Registration #1	2017-08-07	11 mi
Registration #2	2020-08-06	28.971 mi
Registration #3	2021-08-11	28.981 mi
Registration #4		71.777 66
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2035 mm
Height	1485 mm
Length	4505 mm
Wheel base	2650 mm
Kerb weight	1529 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Engine number

D4FBHZ195975