



GX64AOB

report date: 2024-03-28

General information

Make	FORD
Model	S-MAX
Colour	Grey
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-05
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	35
Total items failed	6

MOT #12 2023-07-11 09:50

MOT test number 817970186784

Result ✓ Passed

Next expiry date 2024-08-05

- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2023-07-10 10:07

MOT test number 625825832771

Result ✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** TPMS warning light on
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10**

2022-07-27 08:05

MOT test number

805399052753

Result

✓ Passed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9**

2022-07-21 11:05

MOT test number

782620546194

Result

✗ Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Headlamp insecure (4.1.1 (c))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8**

2021-08-06 11:50

MOT test number

530588784646

Result

✓ Passed

**MOT #7** 2020-12-07 19:49**MOT test number** 664150995814**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #6** 2019-12-11 19:51**MOT test number** 152243125555**Result** ✓ Passed**Advice** Front tyres worn on inside edge**MOT #5** 2019-12-11 19:51**MOT test number** 999053638165**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))**Advice** Front tyres worn on inside edge**MOT #4** 2018-12-15 09:03**MOT test number** 627326747657**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** 3rd row seats folded away, unable to carry out full checks**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #3** 2018-12-15 09:03**MOT test number** 484691891004**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** 3rd row seats folded away, unable to carry out full checks**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #2** 2017-12-21 12:39**MOT test number** 750494011263**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #1** 2017-12-16 10:16**MOT test number** 120935397847**Result** ✗ Failed**Fail** Offside Headlamp aim beam image kick up to the offside (1.8)**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Fail** Nearside Headlamp aim beam image kick up to the offside (1.8)**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-28
Current registration	 XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-19
Last registration	2023-07-11
Complete history	See info



Registration #1	2014-12-19	10 mi
Registration #2	2017-12-16	25.343 mi
Registration #3	2017-12-21	25.551 mi
Registration #4	2018-12-15	33.851 mi
Registration #5	2018-12-15	33.851 mi
Registration #6	2019-12-11	43.816 mi
Registration #7	2019-12-11	43.816 mi
Registration #8	2019-12-11	43.816 mi
Registration #9	2019-12-11	43.816 mi
Registration #10	2019-12-11	43.816 mi
Registration #11	2019-12-11	43.816 mi
Registration #12	2019-12-11	43.816 mi
Registration #13	2019-12-11	43.816 mi
Registration #14	2019-12-11	43.816 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685