





General information

| Make | VAUXHALL |
|---------------------|-----------------------|
| Model | VIVARO L1H1 2700 CDTI |
| Colour | White |
| Year of manufacture | 2017 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------------------------------|
| Max. torque | 300 Nm at 1.750 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.598 cc | 121 - 140 E |
| Cylinders | 4 | 141 - 165 ^F _G |
| Fuel type | Diesel | 166 - 185 H |
| Consumption city | 36.2 mpg | 186 - 225 J |
| Consumption extra urban | 48.7 mpg | 225+ L M |
| Consumption combined | 43.5 mpg | |
| CO2 emission | 170 g/km | |
| CO2 label | Н | |





Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-11-06 |
| Pictures | 16 |
| Listing price | View report |









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-09-03 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 1 |

| MOT #5 | 2023-08-29 12:48 |
|------------------|------------------|
| MOT test number | 217893298333 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-03 |

| MOT #4 | 2023-08-15 14:48 |
|--|------------------|
| MOT test number | 385217337364 |
| Result | 🗙 Failed |
| Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #3 | | 2022-08-26 08:27 |
|----------|--|------------------|
| MOT test | number | 410211755125 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2021-08-26 11:19 |
|-----------------|------------------|
| MOT test number | 689412981314 |
| Result | ✓ Passed |





| MOT #1 | 2020-09-03 09:32 |
|-----------------|------------------|
| MOT test number | 576128954630 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 January 2025 | MOT Expires: 3 September 2024 |
|--|---|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 3 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FET O |
| Category | LAMP |
| Туре | |
| Damage 2 | VAMPLE |
| Date | |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| *********** | |
|--|-------------|
| ********* | |
| | |
| And a second sec | |
| ********** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-09-04 |
| Last registration | 2023-08-29 |
| Complete history | See info |



| Registration #1 | 2017-09-04 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-09-03 | 22.360 mi |
| Registration #3 | 2021-08-26 | 30.442 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 est |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |

More info >





Safety ratings

| NCAP rating | | - June |
|----------------|-----------------|--------|
| Adult | 52% | EURO |
| Children | 91% | |
| Pedestrian | 53% | - |
| Safety systems | 57% | |
| Overall rating | 61% | |
| Video | see crash video | |



| Dimensions & weight | |
|------------------------|---------------------|
| Width | 2283 mm |
| Height | 1971 mm |
| Length | 4998 mm |
| Kerb weight | 1725 kg |
| Max. allowed weight | 2800 kg |
| Additional information | |
| Fuel tank capacity | 80 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | R9M MK - C048048LWZ |