





General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP	0 < 101 A
Max. torque	360 Nm at 1.800 rpm	101 - 120 ^B _C
Cylinders	4	121 - 140
Fuel type	Diesel	141 - 165 F G
Consumption city	29.7 mpg	166 - 185 H
Consumption extra urban	52.3 mpg	186 - 225 J
Consumption combined	40.9 mpg	225+





Internet history

Entry	1
Date	

2021-06-22

Pictures

Listing price

View report

17



source: autotrader.co.uk



MOT history

MOT #17	2021-06-30 13:30
MOT test number	826364398328
Result	✓ Passed
Next expiry date	2022-06-29
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #16	2020-09-05 11:19
MOT test	number 764142617493
Result	✓ Passed
Advice	Nearside Rear Suspension rod ball joint has slight play anti-roll bar tie-pin (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15		2019-09-20 16:05
MOT test	number	107848517119
Result		✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))





MOT #14		2019-09-20 16:05
MOT test	number	403186729705
Result		🗙 Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weake	ned (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Pass wit	th rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #13	2017-12-18 12:43
MOT test number	570606389060
Result	✓ Passed

MOT #12	2016-12-26 15:37
MOT test number	325548514223
Result	✓ Passed
MOT #11	2016-12-05 17:23
MOT test number	946226522745
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #10		2016-06-02 08:47
MOT test	number	817866326524
Result		✓ Passed
Advice Offside Front Tyre worn close to the legal limit 2mm & worn on outer edge (4.1.E.1) Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) (2.4.G.2)		

МОТ #9	2016-06-02 08:47	
MOT test number	845147439216	
Result	🗙 Failed	
Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting (2.4.G.2)	in excessive movement	
Pass with rectificationOffside Headlamp aim too high (1.8)		
Advice Offside Front Tyre worn close to the legal limit 2mm & worn on outer edge (4.1.E.1)		

MOT #8		2015-05-16 09:44
MOT test	number	956056235126
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	O/s/r tyre scrubbed off inner edge	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Front discs wearing thin	



DE08TDU
report date: 2024-03-29

MOT #7	2015-05-09 11:33
MOT test number	538299325101
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice O/s/r tyre scrubbed off inner edge	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Notice Front discs wearing thin	

MOT #6	2014-05-24 11:22
MOT test number	606474044162
Result	✓ Passed
Notice O/s/r tyre scrubbing on inner edge	

MOT #5	2014-05-24 09:59
MOT test number	518184644135
Result	🗙 Failed
NoticeO/s/r tyre scrubbing on inner edgeFailWindscreen washer provides insufficient washer liquid (8.2.3)	



DEO8TDU report date: 2024-03-29

MOT #4		2013-05-13 09:51
MOT test	number	765253133142
Result		✓ Passed
Notice	Front tyres starting to split inner side walls	
Advice (2.4.G.2)	Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excess	sive movement
Notice	Off side rear tyre starting to go out of shape	
Notice	Nail in offside front tyre	
Advice (2.4.G.2)	Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessiv	ve movement

МОТ #3	2012-05-29 12:32
MOT test number	889300152143
Result	✓ Passed

MOT #2		2011-04-11 16:19
MOT test	number	837431701194
Result		✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Notice	Front wipers smearing	
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





MOT #1	2011-04-07 09:15
MOT test number	699187091075
Result	🗙 Failed
Notice Front wipers smearing	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



DEO8TDU report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-15
Last registration	2021-06-30
Complete history	See info



Registration #1	2008-04-15	9 mi
Registration #2	2011-04-07	28.416 mi
Registration #3	2011-04-11	28.420 mi
Registration #4	2012-05-29	47.378 mi
Registration #5	2013-05-13	70.986 mi
Registration #6	2014-05-24	88.610 mi
Registration #7	2014-05-24	88.610 mi
Registration #8	2015-05-09	108.638 mi
Registration #9	2015-05-16	109.136 mi
Registration #10	2016-06-02	145.071 mi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi
Registration #18		01.207 est
Registration #19		



DEO8TDU report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1532 kg
Max. allowed weight	2065 kg
Additional information	
Additional information Fuel tank capacity	61 I
	61 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4