



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Black
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-07-03
Pictures	20
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

MOT expiry date	2024-09-06
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	7

**MOT #17** 2023-09-07 09:20**MOT test number** 678362790125**Result** ✓ Passed**Next expiry date** 2024-09-06**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** N/s/f head light damaged**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #16** 2023-09-07 09:20**MOT test number** 814260094039**Result** ✗ Failed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** N/s/f head light damaged**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #15** 2022-06-29 11:02**MOT test number** 581525356730**Result** ✓ Passed**MOT #14** 2021-08-21 11:16**MOT test number** 127872612767**Result** ✓ Passed**MOT #13** 2020-09-12 12:04**MOT test number** 841337497235**Result** ✓ Passed**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2019-09-02 11:37**MOT test number** 456164224828**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Non-obligatory mirror housing slightly insecure**MOT #11** 2018-09-04 11:22**MOT test number** 845300161897**Result** ✓ Passed

**MOT #10** 2018-09-03 09:16**MOT test number** 932512926689**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**MOT #9** 2017-09-11 15:07**MOT test number** 541350957948**Result** ✓ Passed**MOT #8** 2016-09-10 07:37**MOT test number** 751068694134**Result** ✓ Passed**MOT #7** 2016-09-10 07:37**MOT test number** 934064093497**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Stop lamp not working (1.2.1b)**MOT #6** 2015-09-14 11:07**MOT test number** 427951412308**Result** ✓ Passed**MOT #5** 2014-09-15 11:30**MOT test number** 238568054247**Result** ✓ Passed

**MOT #4** 2013-08-05 17:11**MOT test number** 916327013248**Result** ✓ Passed**MOT #3** 2012-10-11 16:05**MOT test number** 766495082229**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Items removed from driver's view prior to test
- Notice** Both front tyres wearing on outer edge recommend have both tyres changed as soon as possible and front wheel alignment
- Notice** N/s/f tyre close to balding but legal at time of inspection
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Front brake discs heavily lipped
- Notice** Rear brake discs slightly lipped and scored

**MOT #2** 2011-09-28 11:55**MOT test number** 565101771230**Result** ✓ Passed

- Notice** 2 rear cabin seats folded down not allowing full inspection of 2 rear adult seat belts
- Notice** Front brake discs slightly lipped
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #1** 2010-09-27 09:40**MOT test number** 320940070249**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
6 September 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	6 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-28
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2007-09-28	18 mi
Registration #2	2010-09-27	16.678 mi
Registration #3	2011-09-28	22.693 mi
Registration #4	2012-10-11	29.888 mi
Registration #5	2013-08-05	33.232 mi
Registration #6	2014-09-15	44.344 mi
Registration #7	2015-09-14	47.047 mi
Registration #8	2016-09-10	49.280 mi
Registration #9	2016-09-10	49.280 mi
Registration #10	2017-09-11	51.498 mi
Registration #11	2018-09-11	51.498 mi
Registration #12	2018-09-11	51.498 mi
Registration #13	2018-09-11	51.498 mi
Registration #14	2018-09-11	51.498 mi
Registration #15	2018-09-11	51.498 mi
Registration #16	2018-09-11	51.498 mi
Registration #17	2018-09-11	51.498 mi
Registration #18	2018-09-11	51.498 mi
Registration #19	2018-09-11	51.498 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZU948780