





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	Silver
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1


Date 2021-10-21

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-04
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	40
Total items failed	4

MOT #14		2023-12-05 12:09
MOT test i	number	832093173866
Result		✓ Passed
Next expir	y date	2024-12-04
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge Tread dep	oth at 2mm (5.2.3 (e))
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Brakes noisy when applied (drums fitted)	

MOT #13		2023-12-05 12:09
MOT test	number	747719816448
Result		× Failed
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Brakes noisy when applied (drums fitted)	
Advice Nearside Rear Nail in tyre		
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge Tread depth at 2mm (5.2.3 (e))		
Pass wit	h rectification Offside Front Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #12 2022-11-07 12:59

MOT test number 813362268667

Result ✓ Passed

Advice Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Coolant level low.

Advice Rear Exhaust mounting defective broken but exhaust still secure (6.1.2 (a))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))

Advice Wheel trims fitted x4

MOT #11 2022-11-04 16:55

MOT test number 685049618216

Result X Failed

Advice Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Coolant level low.

Advice Rear Exhaust mounting defective broken but exhaust still secure (6.1.2 (a))

Advice Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Wheel trims fitted x4

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt major split (5.3.4 (b) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-28

Passed

× Failed

MOT #10 2021-10-21 16:32

MOT test number 800191812925

Result ✓ Passed

Advice Osf lower arm ball joint dust cover deteriorated

MOT #9 2021-02-15 10:42

MOT test number 351855744808

Advice Coolant level low

Result

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #8 2021-02-15 10:42

MOT test number 779678091992

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Coolant level low

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #7 2019-12-14 12:36

MOT test number 964518224452

Result \rightarrow Passed

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #6

MOT test number

842524542095

Result

Advice Nearside Rear Nail in tyre

Advice Items removed from driver's view prior to test

MOT #5 2018-02-13 12:06 **MOT** test number 812827166115 Result ✓ Passed Offside Rear Tyre worn close to the legal limit tyre on 2-3mm 185/65/15 (4.1.E.1) **Advice** Advice Front brake fluctuating, but not excessively both front (3.7.B.3) Advice Nearside Rear Tyre worn close to the legal limit tyre on 1.6-3mm & has got a nail in tyre tread/underiflated (4.1.E.1) Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice Metal exhaust mounting broken & not fully secure

MOT #4	2017-04-04 16:25
MOT test number	532350262220
Result	✓ Passed
MOT #3	2017-04-04 09:19
MOT test number	185788746969
Result	X Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #2	2016-04-01 16:16
MOT test number	185639792435
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2015-03-24 08:58

MOT test number 898433185078

Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-08
Last registration	2023-12-05
Complete history	See info



Registration #1	2012-03-08	18 mi
Registration #2	2015-03-24	13.770 mi
Registration #3	2016-04-01	23.423 mi
Registration #4	2017-04-04	35.098 mi
Registration #5	2017-04-04	35.098 mi
Registration #6	2018-02-13	41.006 mi
Registration #7	2019-01-08	44.565 mi
Registration #8	2019-12-14	47.905 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
_		

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/

Number of axles 2

Engine number FSX46410607