



report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-VTEC EX
Colour	Black
Year of manufacture	2016
Top speed	113 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	192 Nm at 4.300 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-11
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #8	2023-04-27 08:17
MOT test number	207424494918
Result	✓ Passed
Next expiry date	2024-05-11

MOT #7	2023-04-26 09:20
MOT test number	136503414410
Result	✗ Failed
Fail	Oil leaking continuously from engine posing a serious risk to road safety (8.4.1 (a) (ii))

MOT #6	2022-05-10 09:11
MOT test number	193014488370
Result	✓ Passed

MOT #5	2021-05-12 16:09
MOT test number	473062539928
Result	✓ Passed

**MOT #4** 2020-08-12 08:14**MOT test number** 549565026877**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2019-09-17 15:12**MOT test number** 366954069671**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Towbar component slightly damaged 7 pin wiring connector (6.1.6 (a))**Advice** Items removed from driver's view prior to test**MOT #2** 2019-09-17 10:28**MOT test number** 730546868010**Result** ✗ Failed**Advice** Towbar component slightly damaged 7 pin wiring connector (6.1.6 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))**Advice** Items removed from driver's view prior to test**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #1	2018-11-21 09:37
MOT test number	396526464623
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
11 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	BP65YXA
Plate since	2019-03-29
Current registration	BP65YXA
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-01-20
Last registration	2023-04-27
Complete history	See info



Registration #1	2016-01-20	6 mi
Registration #2	2018-11-21	18.655 mi
Registration #3	2019-09-17	23.864 mi
Registration #4	2019-09-17	23.865 mi
Registration #5	2020-08-12	27.472 mi
Registration #6	2020-08-12	27.472 mi
Registration #7	2020-08-12	27.472 mi
Registration #8	2020-08-12	27.472 mi
Registration #9	2020-08-12	27.472 mi
Registration #10	2020-08-12	27.472 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1645 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R20A94004726