



report date: 2024-03-28

General information

Make	BMW
Model	120 118D M SPORT
Colour	Grey
Year of manufacture	2010
Top speed	130 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2024-10-10
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	33
Total items failed	0

MOT #12 2023-10-10 15:33

MOT test number 424045835342

Result ✓ Passed

Next expiry date 2024-10-10

Advice Front Tyre worn close to legal limit/worn on edge both tyres worn inner edges (5.2.3 (e))

Advice Rear Tyre worn close to legal limit/worn on edge both rear tyres worn close to inner edges (5.2.3 (e))

MOT #11 2022-10-11 10:31

MOT test number 633563980823

Result ✓ Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2021-09-17 13:16

MOT test number 677407346600

Result ✓ Passed

**MOT #9**

2020-09-18 10:46

MOT test number

628515386813

Result

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Sill covers fitted, unable to check fully for corrosion
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
- Advice** Under trays fitted, unable to check all components

MOT #8

2019-09-18 09:11

MOT test number

888739165041

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin inners (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Undertrays fitted unable to fully check several components
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside headlight case cracked
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7**

2018-09-17 09:06

MOT test number

254505174724

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside headlight bracket broken
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Undertrays fitted unable to fully check several components
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6

2017-09-18 09:23

MOT test number

828636901225

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** All four tyres wearing bald on edges
- Advice** Front Brake pad(s) wearing thin inners (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2016-09-12 08:09

MOT test number

488104834415

Result

✓ Passed

- Advice** Under trays fitted can not check underside properly

**MOT #4** 2015-09-16 13:59**MOT test number** 351599206691**Result** ✓ Passed**MOT #3** 2015-03-18 10:02**MOT test number** 125897475002**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-01-28 08:59**MOT test number** 136848424417**Result** ✓ Passed**MOT #1** 2013-11-22 14:28**MOT test number** 618646723302**Result** ✓ Passed**Notice** Front tyres cracking between treads



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-20
Current registration	
Plate since	2019-06-20

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-10-13
Last registration	2023-10-10
Complete history	See info



Registration #1	2010-10-13	26 mi
Registration #2	2013-11-22	38.170 mi
Registration #3	2014-01-28	38.187 mi
Registration #4	2015-03-18	47.812 mi
Registration #5	2015-09-16	50.870 mi
Registration #6	2016-09-12	59.845 mi
Registration #7	2017-09-18	67.059 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1345 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	86047426