





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|------------------|
| Model | ECOSPORT ST-LINE |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 115 mph |
| 0 - 100 km/h | 12.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 92 kW / 125 HP / 138 BHP |
|-------------------------|--------------------------|
| Max. torque | 170 Nm at 1.400 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 37.9 mpg |
| Consumption extra urban | 50.0 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-03-15

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-03-24 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| MOT #4 | | 2024-03-20 11:25 |
|-----------|--|------------------|
| MOT test | number | 849135296177 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-24 |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #3 | | 2024-03-20 11:25 |
|-------------------------------|--|------------------|
| MOT test number | | 447938554254 |
| Result | | 🗙 Failed |
| Advice Nearside Rear S | nock absorbers has light misting of oil (5.3.2 (b)) | |
| Pass with rectification | Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Advice Nearside Rear C | hild Seat fitted not allowing full inspection of adult belt | |

| MOT #2 | | 2023-03-18 12:34 |
|----------|--|------------------|
| MOT test | number | 846729699958 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



MOT #1 2022-03-12 15:58

MOT test number 123777360734

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 24 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report in the premium report and see all owner registrations. | |
|--|-------------|
| | |
| | |
| | |
| | |
| manage of the same | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | |
| Current registration | IK SIN |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-03-25 |
| Last registration | 2024-03-20 |
| Complete history | See info |



| Registration #1 | 2019-03-25 | 27 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-03-12 | 25.186 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 77% |
| Pedestrian | 58% |
| Safety systems | 55% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|-------------|---------|
| Height | 1713 mm |
| Length | 4096 mm |
| Wheel base | 2519 mm |
| Kerb weight | 1249 kg |

Additional information

| Fuel tank capacity | 52 I |
|--------------------|---------|
| Number of axles | 2 |
| Engine number | KC80937 |

CarCheck.co.uk page 11/11