



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-20
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-05
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	55
Total items failed	17

MOT #25	2023-04-06 10:14
---------	------------------

MOT test number	489093222735
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-04-05
------------------	------------

- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Windscreen slightly damaged/chipped but not affecting driver's view
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #24**

2023-04-05 16:05

MOT test number

842487314991

Result**✗ Failed****Fail** Offside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Windscreen slightly damaged/chipped but not affecting driver's view**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #23**

2022-02-18 09:54

MOT test number

477349094906

Result**✓ Passed****Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Windscreen slightly damaged/chipped but not affecting driver's view**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Service brake fluctuating, but not excessively Nearside and Offside (1.2.1 (e))

**MOT #22**

2022-02-16 09:01

MOT test number

981529846080

Result**✗ Failed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Windscreen slightly damaged/chipped but not affecting driver's view
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

MOT #21

2021-02-18 15:16

MOT test number

300651769957

Result**✓ Passed**

- Advice** Bonnet pull defective
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Cooling fan bearing whining

**MOT #20**

2021-02-18 10:15

MOT test number

678957435468

Result**✗ Failed****Fail** Offside Windscreen washer not working (3.5 (a))**Advice** Cooling fan bearing whining**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Bonnet pull defective**MOT #19**

2020-01-22 11:56

MOT test number

943995309609

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**MOT #18**

2019-02-25 16:11

MOT test number

298245328313

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2018-03-15 16:24

MOT test number

483617581661

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone bush (2.4.G.2)

MOT #16

2018-03-15 12:23

MOT test number

541455966269

Result

✗ Failed

Fail Offside rear brake binding (3.7.B.1)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice 205/55/16 Both rear tyres tread depth getting low

Fail Offside Rear rear parking brake recording little or no effort Sticking calliper 47 Kgs reading (3.7.B.6a)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Wishbone bush (2.4.G.2)

Advice ENGINE OIL LEVEL LOW / 1 X LTR C3 FULL SYNTHETIC OIL ADDED

MOT #15

2017-03-14 14:41

MOT test number

965487245958

Result

✓ Passed

Advice Front Brake pads at 4mm

MOT #14

2017-03-14 12:12

MOT test number

499288838214

Result

✗ Failed

Advice Front Brake pads at 4mm

Fail Windscreen washer provides insufficient washer liquid N/s & O/s (8.2.3)

**MOT #13** 2016-03-05 13:46**MOT test number** 824052281734**Result** ✓ Passed**MOT #12** 2015-03-18 12:03**MOT test number** 488497775036**Result** ✓ Passed**MOT #11** 2014-05-31 10:09**MOT test number** 299941854470**Result** ✓ Passed**MOT #10** 2014-05-31 10:09**MOT test number** 838291954104**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (1.8)**MOT #9** 2013-06-20 12:15**MOT test number** 438861373102**Result** ✓ Passed**MOT #8** 2012-06-25 12:37**MOT test number** 925307372145**Result** ✓ Passed**Advice** Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**MOT #7** 2011-06-27 11:42**MOT test number** 247098771106**Result** ✓ Passed**MOT #6** 2010-06-28 16:52**MOT test number** 242409970119**Result** ✓ Passed**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2009-06-27 10:26**MOT test number** 472168879181**Result** ✓ Passed**MOT #4** 2009-06-27 10:26**MOT test number** 814298679156**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #3** 2008-06-24 11:59**MOT test number** 224226178174**Result** ✓ Passed**MOT #2** 2007-06-28 14:42**MOT test number** 260089977446**Result** ✓ Passed



MOT #1	2006-06-28 16:02
MOT test number	872259276176
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
5 April 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FM02UXZ
Plate since	2024-03-28
Current registration	 FM02UXZ
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-06-28
Last registration	2023-04-06
Complete history	See info



Registration #1	2002-06-28	17 mi
Registration #2	2006-06-28	32.141 mi
Registration #3	2007-06-28	40.125 mi
Registration #4	2008-06-24	47.456 mi
Registration #5	2009-06-27	52.722 mi
Registration #6	2010-06-28	58.852 mi
Registration #7	2011-06-27	66.125 mi
Registration #8	2012-06-25	74.459 mi
Registration #9	2013-06-20	82.360 mi
Registration #10	2014-05-31	89.717 mi
Registration #11	2015-03-18	91.313 mi
Registration #12	2016-03-05	104.553 mi
Registration #13	2017-03-14	111.032 mi
Registration #14	2018-03-14	111.032 mi
Registration #15	2019-03-14	111.032 mi
Registration #16	2020-03-14	111.032 mi
Registration #17	2021-03-14	111.032 mi
Registration #18	2022-03-14	111.032 mi
Registration #19	2023-03-14	111.032 mi
Registration #20	2024-03-14	111.032 mi
Registration #21	2025-03-14	111.032 mi
Registration #22	2026-03-14	111.032 mi
Registration #23	2027-03-14	111.032 mi
Registration #24	2028-03-14	111.032 mi
Registration #25	2029-03-14	111.032 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1230 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AZJ 702054