





### General information

| Make                | CITROEN              |
|---------------------|----------------------|
| Model               | DS3 E-HDI FLAIR ETG6 |
| Colour              | Blue                 |
| Year of manufacture | 2015                 |
| Top speed           | 114 mph              |
| 0 - 60 mph          | 10.7 seconds         |
| Gearbox             | 6 speed automatic    |

## Engine & fuel consumption

| Power                   | 91 BHP              |
|-------------------------|---------------------|
| Max. torque             | 230 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 72.4 mpg            |
| Consumption extra urban | 80.7 mpg            |
| Consumption combined    | 78.5 mpg            |
| CO2 emission            | 94 g/km             |
| CO2 label               | А                   |







# Internet history

Entry 1

Date Pictures 2021-11-26

14

Listing price

View report









source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2024-08-04 |
|--------------------|------------|
| MOT pass rate      | 86 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 1          |
| Total advice items | 10         |
| Total items failed | 0          |

| MOT #7           | 2023-07-31 10:12 |
|------------------|------------------|
| MOT test number  | 232745510906     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-04       |

| MOT #6  | 2022-08-03 09:46 |
|---|------------------|
| MOT test number   | 297153055706     |
| Result  | ✓ Passed         |
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |                  |
| Advice Front Exhaust corroded                             |                  |

| MOT #5   |  | 2022-08-02 14:02 |
|----------|--|------------------|
| MOT test | number   | 926260018785     |
| Result   |  | 🗙 Failed         |
| Advice   | Front Exhaust corroded                                       |                  |
| Advice   | Nearside Rear Coil spring corroded (5.3.1 (b) (i))           |                  |
| MAJOR    | Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |                  |





| MOT #4   |  | 2021-08-05 08:07 |
|----------|--|------------------|
| MOT test | number   | 192878986286     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))    |                  |
| Advice   | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))   |                  |

| MOT #3          | 2019-10-16 11:25 |
|-----------------|------------------|
| MOT test number | 335571155948     |
| Result          | ✓ Passed         |

| MOT #2          | 2018-11-12 16:40 |
|-----------------|------------------|
| MOT test number | 661266963858     |
| Result          | ✓ Passed         |

| MOT #1   | 2018-03-05 13:00 |
|--|------------------|
| MOT test number  | 740131605122     |
| Result   | ✓ Passed         |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) |                  |





Tax & MOT check

|                          | ✓<br>Taxed |                                  | ✓<br>мот            |
|--------------------------|------------|----------------------------------|---------------------|
| Tax due:<br>1 March 2025 |            | <b>Expires:</b><br>4 August 2024 |                     |
| Tax status               |            |                                  | Valid until 1 March |
| Days left                |            |                                  | 306                 |
| MOT expiry date          |            |                                  | 4 August 2024       |
| Full MOT history         |            |                                  | See MOT history     |
| Tax calculation          |            |                                  |                     |
| Vahiela class            |            | 40                               |                     |

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |       |
|----------|---------|-------|
| Date     |         |       |
| Category |         | Lamp  |
| Туре     |         |       |
| Damage 2 |         | AMPL  |
| Date     |         | · · · |
| Category | 1000000 | AMPL  |
| Туре     |         |       |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******   |             |
|--|-------------|
|  |             |
| *******  |             |
| ******   |             |
| **********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this CITROEN had different number plates. |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 9          |
| First mileage registration | 2015-03-11 |
| Last registration          | 2023-07-31 |
| Complete history           | See info   |



| Registration #1 | 2015-03-11 | 19 mi      |
|-----------------|------------|------------|
| Registration #2 | 2018-03-05 | 13.557 mi  |
| Registration #3 | 2018-11-12 | 15.696 mi  |
| Registration #4 | 2019-10-16 | 18.440 mi  |
| Registration #5 | 2021-08-05 | 25.477 mi  |
| Registration #6 |            | 11.177 esi |
| Registration #7 |            | 11.777 esi |
| Registration #8 |            | 11.177 esi |
| Registration #9 |            | 11.777 esi |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 90%             |
| Children       | 85%             |
| Pedestrian     | 43%             |
| Safety systems | 97%             |
| Overall rating | 80%             |
| Video          | see crash video |



| Dimensions & weight    |                  |
|------------------------|------------------|
| Width                  | 1946 mm          |
| Height                 | 1540 mm          |
| Length                 | 4157 mm          |
| Wheel base             | 2595 mm          |
| Kerb weight            | 1055 kg          |
| Max. allowed weight    | 1605 kg          |
| Additional information |                  |
| Fuel tank capacity     | 50 I             |
| Fuel delivery          | Direct Injection |
| Number of doors        | 5                |
| Number of seats        | 5                |
| Engine number          | JBFN0073270      |