

Ford



General information

Make	FORD
Model	TRANSIT 350 EL H/R P/V
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel







Internet history

Entry	1		
Date			

Pictures

2021-07-02

14

Listing price

View report









source: yesauto.com



MOT history

MOT expiry date	2024-09-03
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	12
Total items failed	13

MOT #15		2023-09-04 13:50
MOT test	number	374170072182
Result		✓ Passed
Next expi	ry date	2024-09-03
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #14	2022-07-18 10:51
MOT test number	496456371638
Result	✓ Passed

MOT #2	13	2022-07-14 11:07
MOT te	st number	601251840665
Result		🗙 Failed
Fail	Nearside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	





MOT #12	2021-06-24 10:05	
MOT test number	857805865604	
Result	✓ Passed	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		

MOT #11	2021-06-24 10:05	
MOT test number	736171744837	
Result	× Failed	
Pass with rectification (a) (ii))	Offside Front Position lamp light intensity significantly reduced dip light (4.2.3	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		

MOT #10	2020-08-18 15:53
MOT test number	851787150859
Result	✓ Passed





MOT #9	2020-08-18 15:53
MOT test number	961820753380
Result	× Failed
Pass with rectification all lamps (4.7.1 (b) (ii))	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification ingress of dirt (5.3.4 (b) (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the
Pass with rectification	Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Pass with rectification	Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Pass with rectification	Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Pass with rectification	Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

MOT #8	2019-09-14 08:29
MOT test number	249544594420
Result	✓ Passed
MOT #7	2018-09-14 16:24
MOT test number	918065689802
Result	✓ Passed
MOT #6	2018-09-14 16:24

MOT test number		647019662517
Result		🗙 Failed
Pass with rectification	Offside Rear All position lamps not working (4.2.1 (a))	

MOT #5	2017-09-22 15:00
MOT test number	807777133540
Result	✓ Passed





MOT #4	2017-09-22 15:00
MOT test number	718361697686
Result	× Failed
Pass with rectification	Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
МОТ #3	2016-09-03 10:11
MOT test number	545882689100
Result	✓ Passed
MOT #2	2015-09-03 12:29
MOT test number	187308181061
Result	✓ Passed
Advice Offside Rear Inner tyre worn unevenly	
Advice Nearside Rear In	nner tyre has a nail in
Advice Offside Rear Inn	er tyre has a nail in

MOT #1		2014-09-04 13:03
MOT test number		945407244254
Result		✓ Passed
Advice Nearside C	Dbligatory mirror damaged, but not seriously	y affecting the rear view (8.1.2a)



KV61VXK report date: 2024-03-28

Tax & MOT check

X Untaxed	✓ MOT
Tax expired: 1 January 2024	Expires: 3 September 2024
Tax status	Expired at 1 January 2024
Days left	118 days too late
MOT expiry date	3 September 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2023-09-04
Complete history	See info



Registration #1	2011-09-30	17 mi
Registration #2	2014-09-04	10.393 mi
Registration #3	2015-09-03	14.961 mi
Registration #4	2016-09-03	28.902 mi
Registration #5	2017-09-22	38.353 mi
Registration #6	2017-09-22	38.353 mi
Registration #7	2018-09-14	46.389 mi
Registration #8	2018-09-14	46.389 mi
Registration #9	2019-09-14	55.876 mi
Registration #10		10.200 est
Registration #11		11.777 mi
Registration #12		10.307 est
Registration #13		11.777 mi
Registration #14		10.307 est
Registration #15		11.777 mi
Registration #16		11.117 esi
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2374 mm
Height	2629 mm
Length	6403 mm
Kerb weight	2196 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BS06932