





General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 5008 E-HDI ALLURE |
| Colour | Blue |
| Year of manufacture | 2012 |
| Top speed | 114 mph |
| 0 - 60 mph | 12.6 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 112 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 132 g/km |
| CO2 label | E |







Internet history


Entry 2

Date

Pictures

2023-12-12

8



source: g3remarketing.co.uk

| Entry 1 | |
|---------------|--------------------|
| Date | 2021-08-07 |
| Pictures | 33 |
| Listing price | <u>View report</u> |



source: autotrader.co.uk









MOT history

| MOT expiry date | 2025-01-25 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 9 |
| Failed MOT tests | 5 |
| Total advice items | 25 |
| Total items failed | 10 |

| MOT #14 | 2024-01-18 15:13 |
|------------------|------------------|
| MOT test number | 886721546229 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-25 |

| MOT #13 | 2024-01-17 12:35 |
|---|-----------------------|
| MOT test number | 671896592315 |
| Result | 🗙 Failed |
| Advice Nearside Rear Brake disc worn, but not excessively overheated (1.1.14 (a) (i)) |) |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents t (5.3.4 (b) (ii)) | he ingress of dirt |
| Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side | s (1.1.14 (a) (ii)) |
| Fail (ii))Nearside Front Inner Steering rack gaiter missing or no longer prevents the ingre | ss of dirt (2.1.3 (g) |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i)) | ssive movement |



| BN62ZXC | |
|-------------------------|--|
| report date: 2024-03-29 | |

| MOT #12 | | 2023-01-25 13:01 |
|------------|--|----------------------|
| MOT test i | number | 154143121048 |
| Result | | ✓ Passed |
| Advice | Front Play in steering rack inner joint(s) x2 | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) | |
| Advice | Front Outer Tyre has a cut but not deep enough to reach the ply or cords both si | ides (5.2.3 (d) (i)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both sides (| 1.1.14 (a) (ii)) |

| MOT #11 | 2022-01-26 16:35 |
|----------|--|
| MOT test | number 557560392402 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) |
| Advice | Child Seat fitted not allowing full inspection of adult belt |

| MOT #10 | | 2022-01-26 16:35 |
|---|---|------------------|
| MOT test number | | 201136240175 |
| Result | | 🗙 Failed |
| Advice Child Seat fitted | not allowing full inspection of adult belt | |
| Pass with rectification | Offside Front Headlamp aim too high (4.1.2 (a)) | |
| Pass with rectification | Nearside Front Headlamp aim too low (4.1.2 (a)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) | | |



| MOT #9 | | 2021-01-15 14:57 |
|----------|--|------------------|
| MOT test | number | 573619543683 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #8 | | 2021-01-15 14:57 |
|-------------------------|---|------------------|
| MOT test number | | 683886229833 |
| Result | | 🗙 Failed |
| Advice Offside Front Ty | re worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice Nearside Front T | yre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #7 | 2019-06-21 12:24 |
|-----------------|------------------|
| MOT test number | 991938600450 |
| Result | ✓ Passed |

| MOT #6 | 2018-07-17 10:29 |
|---------------|---|
| MOT test | number 592166765904 |
| Result | ✓ Passed |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) |

| MOT #5 | 2017-07-18 08:31 |
|-----------------|------------------|
| MOT test number | 170274467871 |
| Result | ✓ Passed |





| MOT #4 | | 2017-07-17 11:41 |
|----------|---|-------------------------|
| MOT test | number | 380548447878 |
| Result | | 🗙 Failed |
| Fail No | earside Front Tyre has a bulge, caused by separation or partial failure of it | ts structure (4.1.D.1b) |
| MOT #3 | | 2016-07-19 07:42 |
| MOT test | number | 871812588796 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #2 | | 2015-07-20 14:27 |
|----------|--|------------------|
| MOT test | number | 865561305245 |
| Result | | ✓ Passed |
| Notice | Under-trays fitted obscuring some underside components | |
| Notice | Items removed from driver's view prior to test | |
| Notice | Engine covers fitted obscuring some components in the engine bay | |

| MOT #1 | | | 2015-07-20 14:27 |
|--|-------------------|---|------------------|
| MOT test | number | | 666001505285 |
| Result | | | 🗙 Failed |
| Pass wit | th rectification | Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Notice | Under-trays fitte | d obscuring some underside components | |
| Notice Items removed from driver's view prior to test | | | |
| Notice | Engine covers fit | ted obscuring some components in the engine bay | |



Tax & MOT check

| ✓ Taxed | ✓ MOT Expires: | |
|-----------------------------|---|--|
| 1 August 2024 Tax status | 25 January 2025 Valid until 1 August | |
| Days left | 94 | |
| MOT expiry date | 25 January 2025 | |
| Full MOT history | See MOT history | |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2012-09-30 |
| Last registration | 2024-01-18 |
| Complete history | See info |



| Registration #1 | 2012-09-30 | 26 mi |
|------------------|------------|------------|
| Registration #2 | 2015-07-20 | 35.380 mi |
| Registration #3 | 2016-07-19 | 47.565 mi |
| Registration #4 | 2017-07-17 | 61.182 mi |
| Registration #5 | 2017-07-18 | 61.245 mi |
| Registration #6 | 2018-07-17 | 75.193 mi |
| Registration #7 | 2019-06-21 | 89.775 mi |
| Registration #8 | 2021-01-15 | 99.800 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.707 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.707 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |



Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 79% |
| Pedestrian | 37% |
| Safety systems | 97% |
| Overall rating | 77% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2118 mm |
| Height | 1638 mm |
| Length | 4530 mm |
| Wheel base | 2727 mm |
| Kerb weight | 1688 kg |
| Max. allowed weight | 2250 kg |
| Additional information | |
| Fuel tank capacity | 60 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 13/13 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | JBEG3090347 |