




report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D5 SE SPORT
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-05
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #14	2023-06-13 12:26
MOT test number	184752933039
Result	✓ Passed
Next expiry date	2024-06-15

MOT #13	2023-06-13 12:26
MOT test number	159286799884
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #12	2022-06-14 09:20
MOT test number	812199674539
Result	✓ Passed

MOT #11	2021-06-04 14:48
MOT test number	127240865083
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-06-03 09:15
MOT test number	639532891428
Result	✓ Passed



MOT #9 2019-05-28 14:33

MOT test number 881514009022

Result ✓ Passed

MOT #8 2018-05-21 10:59

MOT test number 155721752731

Result ✓ Passed

MOT #7 2017-06-16 14:10

MOT test number 831645845772

Result ✓ Passed

MOT #6 2016-06-28 11:31

MOT test number 726330035782

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2015-06-22 11:05

MOT test number 116323575175

Result ✓ Passed

MOT #4 2014-06-24 10:53

MOT test number 896465074102

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)



MOT #3 2013-07-17 10:54

MOT test number 586918493120

Result ✓ Passed

MOT #2 2012-07-09 14:00

MOT test number 765031992130

Result ✓ Passed

MOT #1 2012-07-09 12:45

MOT test number 257781592114

Result ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
15 June 2024

Tax status Valid until 1 September

Days left 124

MOT expiry date 15 June 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DY09FAK
Plate since	2024-03-29
Current registration	DY09FAK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-07-21
Last registration	2023-06-13
Complete history	See info



Registration #1	2009-07-21	23 mi
Registration #2	2012-07-09	32.854 mi
Registration #3	2012-07-09	32.854 mi
Registration #4	2013-07-17	45.234 mi
Registration #5	2014-06-24	55.223 mi
Registration #6	2015-06-22	63.776 mi
Registration #7	2016-06-28	71.527 mi
Registration #8	2017-06-16	44.928 mi
Registration #9	2018-06-16	55.223 mi
Registration #10	2019-06-16	63.776 mi
Registration #11	2020-06-16	71.527 mi
Registration #12	2021-06-16	71.527 mi
Registration #13	2022-06-16	71.527 mi
Registration #14	2023-06-16	71.527 mi
Registration #15	2023-06-16	71.527 mi
Registration #16	2023-06-16	71.527 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1449 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

