



report date: 2024-03-28

General information

Make	MINI
Model	ONE ONE D
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	220 Nm at 1.496 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	91.1 mpg
Consumption combined	83.1 mpg
CO2 emission	89 g/km
CO2 label	A





Internet history

Entry 3

Date	2023-12-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 2

Date	2022-11-14
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2023-11-28
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	5
Total items failed	7

MOT #10	2022-11-29 15:47
MOT test number	477330890485
Result	✓ Passed
Next expiry date	2023-11-28

MOT #9	2022-06-18 09:28
MOT test number	351557260880
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing both sides slightly cracking (5.2.3 (d) (ii))

MOT #8	2021-06-09 09:00
MOT test number	171681615097
Result	✓ Passed

MOT #7	2020-06-06 09:46
MOT test number	440249321544
Result	✓ Passed

**MOT #6** 2020-06-06 07:53**MOT test number** 544926887638**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**MOT #5** 2019-06-19 15:01**MOT test number** 132428115766**Result** ✓ Passed**MOT #4** 2019-06-16 10:06**MOT test number** 916613763075**Result** ✗ Failed**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**MOT #3** 2018-06-20 16:05**MOT test number** 153406051672**Result** ✓ Passed

**MOT #2** 2018-06-10 12:25**MOT test number** 956760539626**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing slightly perishing in tread (5.2.3 (d) (i))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-06-10 09:40**MOT test number** 774370558299**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 November 2023

X

MOT

Expired:  
28 November 2023

Tax status	Expired at 1 November 2023
Days left	180 days too late
MOT expiry date	28 November 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-26
Last registration	2022-11-29
Complete history	<a href="#">See info</a>



Registration #1	2014-06-26	16 mi
Registration #2	2017-06-10	29.470 mi
Registration #3	2018-06-10	41.158 mi
Registration #4	2018-06-20	41.380 mi
Registration #5	2019-06-16	52.107 mi
Registration #6	2019-06-19	52.186 mi
Registration #7	2020-06-06	62.158 mi
Registration #8	2020-06-20	62.277 mi
Registration #9	2020-06-20	62.277 mi
Registration #10	2020-06-20	62.277 mi
Registration #11	2020-06-20	62.277 mi
Registration #12	2020-06-20	62.277 mi
Registration #13	2020-06-20	62.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1225 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	50559029