



PK57ZPB

report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-08-19
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	34
Total items failed	9

MOT #18	2024-01-24 12:11
MOT test number	772580448582
Result	✓ Passed
Next expiry date	2025-01-24
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #17	2023-01-25 14:03
MOT test number	801630109024
Result	✓ Passed

**MOT #16**

2023-01-24 10:47

MOT test number

477084290931

Result**✗ Failed****DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #15**

2021-12-18 10:01

MOT test number

221653272170

Result**✓ Passed****MOT #14**

2021-12-14 14:07

MOT test number

653068068310

Result**✗ Failed****MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front foot parking brake has little reserve travel

**MOT #13** 2020-12-22 15:04**MOT test number** 978737769560**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #12** 2019-05-31 17:56**MOT test number** 244048757160**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-05-26 16:06**MOT test number** 332346402474**Result** ✓ Passed**MOT #10** 2017-05-23 17:04**MOT test number** 992602959492**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-05-31 18:08**MOT test number** 617525648596**Result** ✓ Passed



MOT #8	2015-06-01 19:20
MOT test number	429982455194
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2013-11-26 08:29
MOT test number	125020133317
Result	✓ Passed

MOT #6	2013-11-14 12:07
MOT test number	258218513320
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Fail	Nearside Front Brake hose excessively chafed (3.6.B.4d)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Windscreen wiper control missing (8.2.1a)

MOT #5	2012-11-24 16:54
MOT test number	949419122339
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-11-24 16:17**MOT test number** 477439722368**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-11-22 17:23**MOT test number** 849826521311**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-10-26 13:03**MOT test number** 821269190215**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak



MOT #12010-10-26 10:12

MOT test number230499090266

ResultX Failed

Fail

Nearside Front Brake pipe inadequately clipped (3.6.B.1)

Notice

Child seat fitted not allowing full inspection of adult belt

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice

Oil leak

Advice

Inner Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-11-23
Last registration	2024-01-24
Complete history	See info



Registration #1	2007-11-23	21 mi
Registration #2	2010-10-26	59.612 mi
Registration #3	2010-10-26	59.612 mi
Registration #4	2011-11-22	69.534 mi
Registration #5	2012-11-24	79.064 mi
Registration #6	2012-11-24	79.064 mi
Registration #7	2013-11-14	90.599 mi
Registration #8	2013-11-26	90.672 mi
Registration #9	2015-06-01	98.765 mi
Registration #10	2016-05-31	113.267 mi
Registration #11	2016-05-31	113.267 mi
Registration #12	2016-05-31	113.267 mi
Registration #13	2016-05-31	113.267 mi
Registration #14	2016-05-31	113.267 mi
Registration #15	2016-05-31	113.267 mi
Registration #16	2016-05-31	113.267 mi
Registration #17	2016-05-31	113.267 mi
Registration #18	2016-05-31	113.267 mi
Registration #19	2016-05-31	113.267 mi
Registration #20	2016-05-31	113.267 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

