




report date: 2024-09-18

General information

Make	MINI
Model	CLUBVAN COOPER
Colour	Blue
Year of manufacture	2012
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-11-13
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-10
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #10 2024-01-11 09:33

MOT test number 263692269373

Result ✓ Passed

Next expiry date 2025-01-10

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9 2022-10-07 12:37

MOT test number 116732329776

Result ✓ Passed

MOT #8 2022-10-06 13:36

MOT test number 366954024904

Result ✗ Failed

Fail Reversing lamp inoperative (4.6.1 (a))

Fail Upper Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #7 2021-11-22 11:52

MOT test number 997829911847

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #6 2020-11-20 13:14

MOT test number 849191551489

Result ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5 2019-11-22 15:26

MOT test number 576900628908

Result ✓ Passed

MOT #4 2018-11-22 12:58

MOT test number 693658448229

Result ✓ Passed

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear mounting (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear mounting (5.3.4 (a) (i))

MOT #3 2017-11-20 10:42

MOT test number 290296560678

Result ✓ Passed

Advice Offside wiper blade is slightly deteriorated

Advice Offside Rear reflector slightly damaged but function not impaired (1.5.1c)



MOT #2 2016-11-09 09:52

MOT test number 924847614580

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)

MOT #1 2015-11-13 07:50

MOT test number 317098697996

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
10 January 2025

Tax status	Valid until 1 January
-------------------	-----------------------

Days left	88
------------------	----

MOT expiry date	10 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	KM62VPP
Plate since	2019-09-18
Current registration	KM62VPP
Plate since	2019-09-18

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-11-23
Last registration	2024-01-11
Complete history	See info



Registration #1	2012-11-23	29 mi
Registration #2	2015-11-13	25.452 mi
Registration #3	2016-11-09	34.620 mi
Registration #4	2017-11-20	41.969 mi
Registration #5	2018-11-22	48.419 mi
Registration #6	2019-11-22	56.022 mi
Registration #7	2020-01-22	61.277 mi
Registration #8	2020-01-22	61.277 mi
Registration #9	2020-01-22	61.277 mi
Registration #10	2020-01-22	61.277 mi
Registration #11	2020-01-22	61.277 mi
Registration #12	2024-01-11	61.277 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of seats	2
Number of axles	2
Engine number	B341J392