





report date: 2024-03-28

General information

Make	CITROEN	
Model	DS5 HDI DSPORT	
Colour	Black	
Year of manufacture	2012	
Top speed	132 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12




Internet history

Entry 1

 Date
 2021-08-08

 Pictures
 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-04-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #9	2024-04-26 15:30	
MOT test number	470811217146	
Result	× Failed	
Advice Rear Shock absorbers has slight external damage to the casing Both (5.3.2	(b))	
Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))		
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))		
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))		
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))		

MOT #8	2023-04-18 09:32
MOT test number	867243260048
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



MOT #7 2023-04-13 12:50

MOT test number 151997761921

Result X Failed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #6 2022-03-05 10:40

MOT test number 119937731166

Advice Play in steering rack inner joint(s)

MOT #5 2021-03-09 12:52

MOT test number 390932381701

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4 2019-09-09 11:48

MOT test number 518534704140

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2017-10-11 10:24

MOT test number 235452083622

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #2

MOT test number

752776831060

Result

Advice Undertrays fitted

MOT #1

MOT test number

258244889932

Result

Advice Under trays fitted obscuring testable items.

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 17 April 2024



X MOT

Expired: 17 April 2024

Tax status	Expired at 17 April 2024
Days left	12 days too late
MOT expiry date	17 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CONTRACTOR CONT	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NE ZIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-11-29
Last registration	2024-04-26
Complete history	See info



Registration #1	2012-11-29	9 mi
Registration #2	2015-11-20	87.662 mi
Registration #3	2016-11-19	94.203 mi
Registration #4	2017-10-11	98.718 mi
Registration #5	2019-09-09	115.661 mi
Registration #6	2021-03-09	124.700 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		0.777-46

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZD4029049

CarCheck.co.uk page 12/12