



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008 HDI SPORT
Colour	Silver
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2024-01-10
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-07
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	22
Total items failed	19

MOT #19	2024-01-08 15:32
MOT test number	371236250432
Result	✓ Passed
Next expiry date	2025-01-07

MOT #18	2023-01-26 11:11
MOT test number	792996437057
Result	✓ Passed

MOT #17	2023-01-26 11:11
MOT test number	128556965793
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #16	2022-02-10 16:23
MOT test number	545903593418
Result	✓ Passed

**MOT #15** 2022-02-10 11:47**MOT test number** 735849747358**Result** ✗ Failed

- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #14 2021-02-15 15:17**MOT test number** 817828982892**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2021-02-04 15:18**MOT test number** 526008106413**Result** ✗ Failed

- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively and offside (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))

MOT #12 2019-11-27 15:10**MOT test number** 389185933012**Result** ✓ Passed

**MOT #11** 2019-11-27 09:59**MOT test number** 564192291245**Result** ✗ Failed**Fail** Nearside Rear Seat belt not functioning as intended (7.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-04-10 07:49**MOT test number** 910679217886**Result** ✓ Passed**MOT #9** 2019-04-08 16:43**MOT test number** 201566456007**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #8** 2018-04-26 14:34**MOT test number** 357805298793**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Undertray(s) fitted

**MOT #7**

2018-04-26 08:03

MOT test number

564738590559

Result**✗ Failed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rears (3.5.1i)
- Advice** Brake pad(s) wearing thin Both rear inner pads look low (3.5.1g)
- Advice** Front Undertray insecure
- Advice** Rear brake fluctuating, but not excessively (3.7.B.3)
- Fail** Front brake application uneven (3.7.B.2)
- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both fronts (3.5.1i)
- Advice** Undertray(s) fitted
- Advice** Brake pad(s) wearing thin Both front inner pads look low (3.5.1g)
- Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #6

2017-04-25 11:25

MOT test number

850478429115

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit on limit (4.1.E.1)

MOT #5

2016-04-27 16:01

MOT test number

432069808800

Result**✓ Passed**

**MOT #4** 2016-04-27 08:57**MOT test number** 691275382069**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #3** 2015-04-29 16:39**MOT test number** 295289115451**Result** ✓ Passed**MOT #2** 2015-04-29 10:15**MOT test number** 678769515136**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2014-05-02 16:27**MOT test number** 977812424110**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2011-06-12
Last registration	2024-01-08
Complete history	See info



Registration #1	2011-06-12	22 mi
Registration #2	2014-05-02	31.841 mi
Registration #3	2015-04-29	39.693 mi
Registration #4	2015-04-29	39.693 mi
Registration #5	2016-04-27	49.186 mi
Registration #6	2016-04-27	49.186 mi
Registration #7	2017-04-25	57.424 mi
Registration #8	2018-04-26	68.674 mi
Registration #9	2018-04-26	68.677 mi
Registration #10	2019-04-08	78.207 mi
Registration #11	2019-04-10	78.207 mi
Registration #12	2019-04-10	78.207 mi
Registration #13	2019-04-10	78.207 mi
Registration #14	2019-04-10	78.207 mi
Registration #15	2019-04-10	78.207 mi
Registration #16	2019-04-10	78.207 mi
Registration #17	2019-04-10	78.207 mi
Registration #18	2019-04-10	78.207 mi
Registration #19	2019-04-10	78.207 mi
Registration #20	2019-04-10	78.207 mi
Registration #21	2019-04-10	78.207 mi
Registration #22	2019-04-10	78.207 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1577 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER3024943