



HYUNDAI

UK **R062ZGW**


report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-02
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	23
Total items failed	2

MOT #12	2023-08-29 15:09
MOT test number	164253884672
Result	✓ Passed
Next expiry date	2024-09-26
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11	2022-09-15 14:46
MOT test number	189735024450
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))
Advice	Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))



MOT #10	2022-09-14 07:26
MOT test number	340321122631
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))
MAJOR	Offside Front Inner Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))
Advice	Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))
MAJOR	Position lamp not working Both front (4.2.1 (a) (ii))

MOT #9	2021-09-15 09:54
MOT test number	628769668813
Result	✓ Passed
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #8	2020-09-22 14:49
MOT test number	789048549934
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both wearing edges (235/60r18 (5.2.3 (e))
Advice	Engine covers and undertrays fitted

MOT #7	2019-09-26 08:50
MOT test number	280047105281
Result	✓ Passed

MOT #6	2019-09-26 08:50
MOT test number	314406067810
Result	✗ Failed
Pass with rectification	Offside Rear Position lamp adversely affected by the operation of another lamp stop/tail light bulb incorrectly fitted,removed and refitted correctly (4.2.3 (c))



MOT #5	2018-09-21 14:57
MOT test number	342370366200
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Spare tyre defective cords exposed

MOT #4	2017-09-23 10:04
MOT test number	565387016540
Result	✓ Passed
Advice	Offside Front tyre has a worn inner edge. soon will show cords
Advice	Offside Rear tyre has a worn inner edge
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #3	2017-09-22 08:35
MOT test number	267120609133
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear tyre has a worn inner edge
Fail	Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Advice	Offside Front tyre has a worn inner edge. soon will show cords

MOT #2	2016-09-26 08:07
MOT test number	352233281625
Result	✓ Passed



MOT #1 2015-09-15 09:24

MOT test number 356304653302

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
26 September 2024

Tax status Valid until 1 September

Days left 126

MOT expiry date 26 September 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RO62ZGW
Plate since	2024-03-28
Current registration	RO62ZGW
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-27
Last registration	2023-08-29
Complete history	See info



Registration #1	2012-09-27	13 mi
Registration #2	2015-09-15	28.895 mi
Registration #3	2016-09-26	41.212 mi
Registration #4	2017-09-22	53.556 mi
Registration #5	2017-09-23	53.556 mi
Registration #6	2018-09-21	64.405 mi
Registration #7	2019-09-26	73.747 mi
Registration #8	2019-09-26	73.747 mi
Registration #9	2019-09-26	73.747 mi
Registration #10	2019-09-26	73.747 mi
Registration #11	2019-09-26	73.747 mi
Registration #12	2019-09-26	73.747 mi
Registration #13	2019-09-26	73.747 mi
Registration #14	2019-09-26	73.747 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4HBBU540258