



PEUGEOT



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | PEUGEOT        |
| Model               | 206 ZEST 3     |
| Colour              | Black          |
| Year of manufacture | -              |
| Top speed           | 106 mph        |
| 0 - 60 mph          | 12.2 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 74 BHP              |
| Max. torque             | 120 Nm at 3.400 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 33.6 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 44.8 mpg            |



LABEL UNKNOWN



Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-15                  |
| Pictures      | 5                           |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-14                  |
| Pictures      | 5                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                         |                                                                                                                        |
|-------------------------|------------------------------------------------------------------------------------------------------------------------|
| <b>MOT #21</b>          | 2022-10-10 14:46                                                                                                       |
| <b>MOT test number</b>  | 440010169344                                                                                                           |
| <b>Result</b>           | ✓ Passed                                                                                                               |
| <b>Next expiry date</b> | 2023-10-10                                                                                                             |
| <b>Advice</b>           | Front Oil leak, but not excessive (8.4.1 (a) (i))                                                                      |
| <b>Advice</b>           | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement most rear (5.3.4 (a) (i)) |
| <b>Minor</b>            | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))        |
| <b>Advice</b>           | Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement most rear (5.3.4 (a) (i))  |

|                        |                  |
|------------------------|------------------|
| <b>MOT #20</b>         | 2021-10-11 11:17 |
| <b>MOT test number</b> | 819024040936     |
| <b>Result</b>          | ✓ Passed         |

|                        |                                                                                                    |
|------------------------|----------------------------------------------------------------------------------------------------|
| <b>MOT #19</b>         | 2020-12-19 11:38                                                                                   |
| <b>MOT test number</b> | 262287706846                                                                                       |
| <b>Result</b>          | ✓ Passed                                                                                           |
| <b>Minor</b>           | Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| <b>Advice</b>          | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                          |
| <b>Advice</b>          | Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))                                  |

|                        |                                                                                                    |
|------------------------|----------------------------------------------------------------------------------------------------|
| <b>MOT #18</b>         | 2020-01-04 10:12                                                                                   |
| <b>MOT test number</b> | 574282850351                                                                                       |
| <b>Result</b>          | ✓ Passed                                                                                           |
| <b>Advice</b>          | Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))      |
| <b>Minor</b>           | Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

**MOT #17** 2019-01-04 09:42**MOT test number** 666109093501**Result** ✓ Passed**Advice** Offside rear wheel arch plastic loose**MOT #16** 2019-01-04 09:09**MOT test number** 186197151759**Result** ✗ Failed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Offside rear wheel arch plastic loose**MOT #15** 2017-12-21 12:08**MOT test number** 977604776476**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)**MOT #14** 2017-12-21 12:08**MOT test number** 568878740962**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #13** 2017-01-12 17:30**MOT test number** 693938029360**Result** ✓ Passed**Advice** Nearside Front tyre worn on edges slightly

**MOT #12** 2015-12-18 09:48**MOT test number** 898508180371**Result** ✓ Passed**MOT #11** 2014-12-19 09:51**MOT test number** 208493454324**Result** ✓ Passed**Notice** Rear exhaust box corroded**MOT #10** 2013-12-23 13:24**MOT test number** 518347453361**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #9** 2013-12-23 09:17**MOT test number** 486807653441**Result** ✗ Failed**Fail** Centre Rear Seat belt retracting mechanism defective (5.2.5b)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #8** 2012-12-22 11:40**MOT test number** 248367852375**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #7** 2012-12-22 10:17**MOT test number** 456047852315**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front Side repeater incorrect colour (1.4.A.2f)**MOT #6** 2011-12-22 09:48**MOT test number** 188166351311**Result** ✓ Passed**Notice** Off side rear tyre showing signs of ageing cracks**MOT #5** 2010-12-21 13:30**MOT test number** 492205250351**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2010-12-21 09:39**MOT test number** 754875350365**Result** ✗ Failed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



|                 |                                                                                       |
|-----------------|---------------------------------------------------------------------------------------|
| MOT #3          | 2010-03-06 10:13                                                                      |
| MOT test number | 562685260040                                                                          |
| Result          | ✓ Passed                                                                              |
| Advice          | Offside Front Brake pad(s) wearing thin (3.5.1g)                                      |
| Advice          | Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)  |
| Advice          | Nearside Front Brake pad(s) wearing thin (3.5.1g)                                     |
| Advice          | Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2009-03-04 16:39 |
| MOT test number | 190283469026     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2008-03-07 15:01 |
| MOT test number | 102037968444     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2024-03-29 |
| Current registration | *****      |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 24                       |
| First mileage registration | 2005-03-01               |
| Last registration          | 2022-10-10               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2005-03-01 | 20 mi     |
| Registration #2  | 2008-03-07 | 10.942 mi |
| Registration #3  | 2009-03-04 | 17.765 mi |
| Registration #4  | 2010-03-06 | 26.623 mi |
| Registration #5  | 2010-12-21 | 31.486 mi |
| Registration #6  | 2010-12-21 | 31.486 mi |
| Registration #7  | 2011-12-22 | 33.184 mi |
| Registration #8  | 2012-12-22 | 35.205 mi |
| Registration #9  | 2012-12-22 | 35.205 mi |
| Registration #10 | 2013-12-23 | 37.837 mi |
| Registration #11 | 2013-12-23 | 37.837 mi |
| Registration #12 | 2014-12-19 | 39.879 mi |
| Registration #13 | 2015-03-20 | 40.000 mi |
| Registration #14 | 2015-03-20 | 40.000 mi |
| Registration #15 | 2015-03-20 | 40.000 mi |
| Registration #16 | 2015-03-20 | 40.000 mi |
| Registration #17 | 2015-03-20 | 40.000 mi |
| Registration #18 | 2015-03-20 | 40.000 mi |
| Registration #19 | 2015-03-20 | 40.000 mi |
| Registration #20 | 2015-03-20 | 40.000 mi |
| Registration #21 | 2015-03-20 | 40.000 mi |
| Registration #22 | 2015-03-20 | 40.000 mi |
| Registration #23 | 2015-03-20 | 40.000 mi |
| Registration #24 | 2015-03-20 | 40.000 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1652 mm |
| Height              | 1433 mm |
| Length              | 3822 mm |
| Wheel base          | 2445 mm |
| Kerb weight         | 1025 kg |
| Max. allowed weight | 1450 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                        |             |
|------------------------|-------------|
| <b>Number of axles</b> | 2           |
| <b>Engine number</b>   | FSR95191649 |