





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|------------------|
| Model | GRANDLAND SE S/S |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 117 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 128 BHP |
|----------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.199 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption combined | 44.1 mpg |
| CO2 emission | 120 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-16

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

PE19FXG
report date: 2024-03-29

| MOT expiry date | 2025-03-15 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 4 |

| MOT #5 | 2024-03-05 13:30 |
|---|------------------|
| MOT test number | 169867410107 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-15 |
| Advice Front Tyre worn close to legal limit/worn on edge both side front on | 2mm (5.2.3 (e)) |

| MOT #4 | 2024-03-05 11:57 |
|---|------------------|
| MOT test number | 815142490321 |
| Result | X Failed |
| Advice Front Tyre worn close to legal limit/worn on edge both side front on 2mm (5.2. | 3 (e)) |
| Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Fail Nearside Front Headlamp aim unable to be tested dipped beam not working (4.1.2 | 2 (b)) |
| Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |

| MOT #3 | 2023-03-16 15:00 |
|----------------------------------|------------------|
| MOT test number | 748863318316 |
| Result | ✓ Passed |
| Advice Offside Rear Nail in tyre | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-03-01 09:08 **MOT test number** 970063972131 ✓ Passed Result MOT #1 2022-02-25 11:32 729094866203 **MOT test number X** Failed Result Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 15 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



PE19FXG
report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

| Damage 2 | |
|----------|--|
| Date | |
| Category | |

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



PE19FXG
report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VAUXHALL had different number plates. mber of plates -More info >

CarCheck.co.uk page 8/11



PE19FXG
report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2019-03-15 |
| Last registration | 2024-03-05 |
| Complete history | See info |



| Registration #1 | 2019-03-15 | 7 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-02-25 | 27.318 mi |
| Registration #3 | 2022-03-01 | 27.318 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 87% |
| Pedestrian | 63% |
| Safety systems | 60% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 1856 mm |
|----------------------|-------------|
| | |
| Height | 1609 mm |
| | |
| Length | 4477 mm |
| | 1177 111111 |
| Max. allowed weight | 1900 kg |
| rian, allowed weight | 1300 Kg |

Additional information

| Number of seats | 5 |
|-----------------|-------------------|
| Number of axles | 2 |
| Engine number | 10XVA80084156 LES |

CarCheck.co.uk page 11/11