



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Blue
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





## MOT history

MOT expiry date	2021-03-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	49
Total items failed	6

MOT #18 2020-03-26 12:05

MOT test number 547096958078

Result ✓ Passed

Next expiry date 2021-03-29

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17 2020-03-24 11:00

MOT test number 842499428864

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2019-03-29 09:13

**MOT test number**

400521733212

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Parking brake lever defective but can be satisfactorily operated excessive travel (1.1.6 (d))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Child Seat fitted not allowing full inspection of adult belt

**Advice**

Slight bind on front brakes

**MOT #15**

2018-03-29 10:37

**MOT test number**

376930745673

**Result**

✓ Passed

**Advice**

Parking brake lever has little reserve travel (3.1.6b)

**Advice**

Underside of vehicle becoming corroded

**MOT #14**

2018-03-26 14:08

**MOT test number**

855722397028

**Result**

✗ Failed

**Fail**

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Fail**

Central Exhaust has a major leak of exhaust gases (7.1.2)

**Advice**

Underside of vehicle becoming corroded



MOT #13

2017-03-08 14:46

MOT test number

483330050732

Result		✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Slight engine oil leak	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #12

2016-03-22 15:58

MOT test number

604444875543

Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	



<b>MOT #11</b>	2015-03-20 09:08
<b>MOT test number</b>	215129475095
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Notice</b>	Slight bind on n/s/f brake

<b>MOT #10</b>	2014-03-20 10:01
<b>MOT test number</b>	146039074493
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2013-03-18 16:51
<b>MOT test number</b>	467587873096
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Brake pipe slightly corroded (3.6.B.2c)

<b>MOT #8</b>	2013-03-18 09:17
<b>MOT test number</b>	929117273032
<b>Result</b>	✗ Failed
<b>Notice</b>	Slight bind on n/s/f brake
<b>Fail</b>	Offside front brake binding (3.7.B.1)
<b>Advice</b>	Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #7**

2012-03-21 13:39

**MOT test number**

836361582028

**Result**

✓ Passed

- Notice** O/s/r tyre slightly perished
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** O/s of steering rack slightly oily
- Notice** N/s/r brake disc worn

**MOT #6**

2012-03-21 09:24

**MOT test number**

509561882055

**Result**

✗ Failed

- Notice** N/s/r brake disc worn
- Notice** O/s of steering rack slightly oily
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** O/s/r tyre slightly perished
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Slight bin d on n/s/f brake

**MOT #5**

2011-03-11 10:35

**MOT test number**

639470271050

**Result**

✓ Passed

**MOT #4**

2011-03-11 08:57

**MOT test number**

949020471068

**Result**

✗ Failed

- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #3	2010-03-17 16:45
MOT test number	603076070058
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2009-03-18 13:01
MOT test number	362167679076
Result	✓ Passed

MOT #1	2008-03-12 16:57
MOT test number	833132478087
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
26 January 2021

X

MOT

Expired:  
29 March 2021

Tax status	Expired at 26 January 2021
Days left	1188 days too late
MOT expiry date	29 March 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-29
Last registration	2020-03-26
Complete history	<a href="#">See info</a>



Registration #1	2005-03-29	27 mi
Registration #2	2008-03-12	20.494 mi
Registration #3	2009-03-18	26.147 mi
Registration #4	2010-03-17	32.501 mi
Registration #5	2011-03-11	39.532 mi
Registration #6	2011-03-11	39.532 mi
Registration #7	2012-03-21	45.525 mi
Registration #8	2012-03-21	45.528 mi
Registration #9	2013-03-18	51.686 mi
Registration #10	2013-03-18	51.086 mi
Registration #11	2019-03-20	55.377 mi
Registration #12	2019-03-20	55.377 mi
Registration #13	2019-03-20	55.377 mi
Registration #14	2019-03-20	55.377 mi
Registration #15	2019-03-20	55.377 mi
Registration #16	2019-03-20	55.377 mi
Registration #17	2019-03-20	55.377 mi
Registration #18	2019-03-20	55.377 mi
Registration #19	2019-03-20	55.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1215 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	3ZZU675172