



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	2007
Top speed	144 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-10-17
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-10-10
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-28
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	22
Total items failed	21

MOT #22	2022-12-29 12:31
MOT test number	756368114856
Result	✓ Passed
Next expiry date	2023-12-28

MOT #21	2021-11-26 16:40
MOT test number	831815872663
Result	✓ Passed

MOT #20	2021-11-26 09:51
MOT test number	870493455052
Result	✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #19**

2021-09-22 15:57

MOT test number

682191472147

Result

✓ Passed

Advice Brake pipe corroded, covered in grease or other material both rear brake pipes corroded (1.1.11 (c))

Advice Both front brake back plates corroded

Advice Oil leak, but not excessive gear box oil leak (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))

MOT #18

2021-09-13 16:23

MOT test number

354338773610

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))

Fail Rear fog lamp obviously incorrectly positioned (4.5.4 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Both front brake back plates corroded

Fail Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen o/s/f washer jet inop (3.5 (a))

Advice Oil leak, but not excessive gear box oil leak (8.4.1 (a) (i))

Advice Brake pipe corroded, covered in grease or other material both rear brake pipes corroded (1.1.11 (c))

MOT #17

2020-08-26 08:14

MOT test number

629643403630

Result

✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2020-08-25 14:38**MOT test number** 340576860919**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #15** 2019-08-22 15:45**MOT test number** 292277997051**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both rears (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**MOT #14** 2018-08-08 13:18**MOT test number** 489168007212**Result** ✓ Passed**MOT #13** 2018-08-08 10:50**MOT test number** 523989506160**Result** ✗ Failed**Fail** Windscreen washer not working (3.5 (a))**Fail** Exhaust system insecure (6.1.2 (a))**MOT #12** 2017-07-19 14:59**MOT test number** 231923326249**Result** ✓ Passed

**MOT #11** 2017-07-18 12:11**MOT test number** 247273145533**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2016-07-20 14:15**MOT test number** 598407600975**Result** ✓ Passed**MOT #9** 2016-07-20 11:00**MOT test number** 829213373097**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint front arm (2.4.G.2)**MOT #8** 2015-07-07 10:56**MOT test number** 367828885124**Result** ✓ Passed**MOT #7** 2015-07-06 15:54**MOT test number** 596277085148**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Centre Exhaust system not adequately supported (7.1.1)

**MOT #6** 2014-06-23 10:39**MOT test number** 408004774127**Result** ✓ Passed**MOT #5** 2014-06-19 09:52**MOT test number** 985910074113**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**MOT #4** 2013-05-09 15:03**MOT test number** 816099423189**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2012-05-04 09:37**MOT test number** 228305822134**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2011-05-10 11:30**MOT test number** 916880431149**Result** ✓ Passed



MOT #1	2010-05-04 09:46
MOT test number	802814220153
Result	✓ Passed
<div>Notice</div> N/S/F tyre wearing on outer edge.	



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-05-03
Last registration	2022-12-29
Complete history	See info



Registration #1	2007-05-03	8 mi
Registration #2	2010-05-04	40.636 mi
Registration #3	2011-05-10	53.349 mi
Registration #4	2012-05-04	65.901 mi
Registration #5	2013-05-09	79.051 mi
Registration #6	2014-06-19	90.355 mi
Registration #7	2014-06-23	90.357 mi
Registration #8	2015-07-06	97.918 mi
Registration #9	2015-07-07	97.921 mi
Registration #10	2016-07-20	103.435 mi
Registration #11	2016-07-20	103.435 mi
Registration #12	2017-07-18	108.333 mi
Registration #13	2017-07-19	108.335 mi
Registration #14	2018-05-20	115.277 mi
Registration #15	2018-05-20	115.277 mi
Registration #16	2018-05-20	115.277 mi
Registration #17	2018-05-20	115.277 mi
Registration #18	2018-05-20	115.277 mi
Registration #19	2018-05-20	115.277 mi
Registration #20	2018-05-20	115.277 mi
Registration #21	2018-05-20	115.277 mi
Registration #22	2018-05-20	115.277 mi
Registration #23	2018-05-20	115.277 mi
Registration #24	2018-05-20	115.277 mi
Registration #25	2018-05-20	115.277 mi



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530868737