



PEUGEOT



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | PEUGEOT |
| Model | 107 ACTIVE |
| Colour | Red |
| Year of manufacture | 2012 |
| Top speed | 98 mph |
| 0 - 60 mph | 14.9 seconds |
| Gearbox | 5 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 68 BHP |
| Max. torque | 93 Nm at 3.600 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 104 g/km |
| CO2 label | B |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-02 |
| MOT pass rate | 75 % |
| MOT passed | 9 |
| Failed MOT tests | 3 |
| Total advice items | 36 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #12 | 2023-07-03 09:46 |
| MOT test number | 634472169114 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-02 |

| | |
|-----------------|---|
| MOT #11 | 2023-05-15 10:54 |
| MOT test number | 996823517741 |
| Result | ✓ Passed |
| Advice | Front Coil spring corroded O/S AND N/S LOWER COILS (5.3.1 (b) (i)) |
| Advice | Rear Exhaust has a minor leak of exhaust gases PIPE AT JOINT AND REAR BOX (6.1.2 (a)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #10 | 2022-05-16 14:41 |
| MOT test number | 931094522632 |
| Result | ✓ Passed |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge ON THE LIMIT (5.2.3 (e)) |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material TO FLEXY (1.1.11 (c)) |

**MOT #9** 2022-05-16 11:12**MOT test number** 266578684433**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material TO FLEXY (1.1.11 (c))**Fail** Rear Exhaust has a major leak of exhaust gases AT JOINT (6.1.2 (a))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge ON THE LIMIT (5.2.3 (e))**MOT #8** 2021-01-08 10:25**MOT test number** 840979791646**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perishing / splitting (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perishing / splitting (5.3.4 (a) (i))**Advice** Front Exhaust mounting defective support bracket corroding (6.1.2 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Fuel filler neck beginning to corrode where filler cap seal meets neck

**MOT #7**

2021-01-08 10:25

MOT test number

167998676346

Result**✗ Failed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perishing / splitting (5.3.4 (a) (i))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))
- Advice** Fuel filler neck beginning to corrode where filler cap seal meets neck
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perishing / splitting (5.3.4 (a) (i))
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Exhaust mounting defective support bracket corroding (6.1.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #6

2019-06-29 11:44

MOT test number

505618561661

Result**✓ Passed**

- Advice** Offside Rear Exhaust mounting defective Exhaust mounting corroded on box (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.62mm also worn excessive on inner edge (155/65r14 (5.2.3 (e)))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both nearside and offside in tread (5.2.3 (d) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both nearside and offside rear bushes (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin Nearside and offside (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm also worn on inner edge (155/65r14 (5.2.3 (e)))

**MOT #5** 2018-06-30 13:46**MOT test number** 142979881384**Result** ✓ Passed**MOT #4** 2017-06-24 10:13**MOT test number** 650626890150**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2.2mm (4.1.E.1)**Advice** Nearside front tyre wearing on edges**Advice** Nearside Front Tyre worn close to the legal limit 1.6mm.155/65r14 (4.1.E.1)**MOT #3** 2016-07-21 13:18**MOT test number** 476391545505**Result** ✓ Passed**Advice** Brake pedal rubber worn.**Advice** Front brake pads getting low.**Advice** Exhaust mounts corroded.**Advice** Front brake discs corroded.**MOT #2** 2015-07-23 09:45**MOT test number** 875704205282**Result** ✓ Passed**MOT #1** 2015-07-22 09:27**MOT test number** 785023905225**Result** ✗ Failed**Fail** Nearside Headlamp aim too far to the right (1.8)**Fail** Offside Headlamp aim too far to the right (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 2 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2012-07-23 |
| Last registration | 2023-07-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-07-23 | 10 mi |
| Registration #2 | 2015-07-22 | 31.509 mi |
| Registration #3 | 2015-07-23 | 31.545 mi |
| Registration #4 | 2016-07-21 | 48.660 mi |
| Registration #5 | 2017-06-24 | 53.071 mi |
| Registration #6 | 2018-06-30 | 57.807 mi |
| Registration #7 | 2019-06-29 | 62.626 mi |
| Registration #8 | 2020-06-29 | 66.377 mi |
| Registration #9 | 2021-06-29 | 69.377 mi |
| Registration #10 | 2022-06-29 | 72.377 mi |
| Registration #11 | 2023-06-29 | 75.377 mi |
| Registration #12 | 2024-06-29 | 78.377 mi |
| Registration #13 | 2025-06-29 | 81.377 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1630 mm |
| Height | 1465 mm |
| Length | 3430 mm |
| Wheel base | 2340 mm |
| Kerb weight | 925 kg |
| Max. allowed weight | 1190 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 7232258 |