





General information

Make	KIA
Model	OPTIMA CRDI 2 LUXE
Colour	White
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.6 mpg
CO2 emission	128 g/km
CO2 label	D







Internet history

Entry 2	
Date	


Pictures

2021-10-28

43

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-10-27

43

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-01
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	27
Total items failed	4

MOT #13		2022-10-21 14:38
MOT test	number	679328732810
Result		✓ Passed
Next expi	ry date	2023-11-01
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))	

MOT #12	2021-11-02 14:12
MOT test number	217727140135
Result	✓ Passed

MOT #11	20	020-12-16 13:10
MOT test	number	337566849997
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	



LD12	PFZ
report date:	2024-03-28

MOT #10		2020-12-14 14:08
MOT test	number	804469183401
Result		🗙 Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #9		2019-12-19 10:49
MOT test	number	368344850591
Result		✓ Passed
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2018-12-18 14:51
MOT test number	502442027611
Result	✓ Passed

MOT #7		2018-12-17 13:26
MOT test	number	399075563553
Result		🗙 Failed
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 225/45r18 (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	





MOT #6		2018-11-21 16:13
MOT test numb	er	107044037097
Result		🗙 Failed
Advice Offsi	ide Rear Nail in tyre	
Pass with rec	tification Offside Headlamp aim too low (4.1.2 (a))	
Advice Exha	aust mid section has impact damage	
Advice Near (a) (ii))	rside Front Brake disc worn, pitted or scored, but not seriously weal	kened inner surface (1.1.14
Advice Offsi	ide Front Service brake binding but not excessively (1.2.1 (f))	
Pass with rec	tification Nearside Headlamp aim too low (4.1.2 (a))	
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR Offsi	ide Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offsi (a) (ii))	ide Front Brake disc worn, pitted or scored, but not seriously weake	ned inner surface (1.1.14

МОТ #5	2018-05-07 14:33
MOT test number	138650841499
Result	✓ Passed
Advice Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1	.i)
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #4	2018-05-07 10:35
MOT test number	594509161835
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Nearside Front Wheel nut(s) missing (4.2.A.1e)	
Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	





MOT #3	2017-05-09 10:58
MOT test number	723801983261
Result	✓ Passed
Advice Tyre worn close to the legal limit both front (4.1.E.1)	
MOT #2	2016-05-02 08:18
MOT test number	574277767107
Result	✓ Passed
MOT #1	2015-04-22 12:15
MOT test number	675602715106
Result	✓ Passed





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damaye 2	e e et al
Date	 1.
Category	 AMP
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second s	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-05-08
Last registration	2022-10-21
Complete history	<u>See info</u>



Registration #1	2012-05-08	28 mi
Registration #2	2015-04-22	28.927 mi
Registration #3	2016-05-02	40.714 mi
Registration #4	2017-05-09	51.366 mi
Registration #5	2018-05-07	58.206 mi
Registration #6	2018-05-07	58.206 mi
Registration #7	2018-11-21	60.801 mi
Registration #8	2018-12-17	60.811 mi
Registration #9		11.777 est
-		10.000 est 10.000 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

Dimensions & weight

Width	1835 mm
Height	1455 mm
Length	4845 mm
Wheel base	2795 mm
Kerb weight	1637 kg
Max. allowed weight	2050 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Engine number	D4FDBH300187