



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE VVT
Colour	Blue
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	111 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-04
Pictures	5
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT #12</b>	2020-12-10 10:29
<b>MOT test number</b>	206108765577
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-12-09
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2019-12-09 13:28
<b>MOT test number</b>	150366676411
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #10</b>	2018-11-06 15:49
<b>MOT test number</b>	530309547714
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2018-07-31 14:11**MOT test number** 873734598938**Result** ✗ Failed**MAJOR** Windscreen wiper not working (3.4 (a))**DANGEROUS** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Windscreen washer not working (3.5 (a))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Rear Registration plate lamp does not illuminate simultaneously with the position lamps both (4.7.2 (a))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #8** 2016-08-09 15:41**MOT test number** 503574356444**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2015-07-09 18:17**MOT test number** 778420295189**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-07-07 17:18**MOT test number** 795578284159**Result** ✓ Passed**MOT #5** 2013-06-06 16:06**MOT test number** 435857753191**Result** ✓ Passed**MOT #4** 2012-06-08 11:21**MOT test number** 698260662179**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Adv on rearfule cap outer cover missing**Notice** Adv on off side rear brake biding**Notice** Adv on off side front tyre on 1.9m and 1.6m on outer edge**MOT #3** 2011-06-18 10:18**MOT test number** 276119261469**Result** ✓ Passed



MOT #2	2011-06-18 10:02
MOT test number	808809761104
Result	✗ Failed
<div><div>Fail</div>Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div>	

MOT #1	2010-06-22 12:13
MOT test number	404113270178
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-06-15
Last registration	2020-12-10
Complete history	<a href="#">See info</a>



Registration #1	2007-06-15	10 mi
Registration #2	2010-06-22	20.352 mi
Registration #3	2011-06-18	24.630 mi
Registration #4	2011-06-18	24.630 mi
Registration #5	2012-06-08	28.951 mi
Registration #6	2013-06-06	32.777 mi
Registration #7	2014-07-07	44.553 mi
Registration #8	2015-06-22	55.333 mi
Registration #9	2016-06-22	66.113 mi
Registration #10	2017-06-22	76.893 mi
Registration #11	2018-06-22	87.673 mi
Registration #12	2019-06-22	98.453 mi
Registration #13	2020-06-22	109.233 mi
Registration #14	2021-06-22	120.013 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2025 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1190 kg
Max. allowed weight	1675 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	D014869
---------------	---------