



report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Black
Year of manufacture	2004
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	24.1 mpg
CO2 emission	273 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-14
Pictures	41
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-12
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	46
Total items failed	6

MOT #21	2023-04-13 10:25
MOT test number	519217472608
Result	✓ Passed
Next expiry date	2024-04-12
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2021-08-02 18:15
MOT test number	567344095236
Result	✓ Passed

MOT #19	2020-10-02 14:11
MOT test number	952308068889
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2020-10-02 10:48**MOT test number** 877487773615**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #17** 2019-10-03 12:07**MOT test number** 410245425555**Result** ✓ Passed

**MOT #16**

2019-01-23 18:06

MOT test number

588718785216

Result

✓ Passed

- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Both exhaust flexis damaged deteriorated
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Catalyst converter heat shields corroded
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside tyre worn on inner edge
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Temporary power steering cap fitted
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #15

2017-08-04 09:28

MOT test number

896241992497

Result

✓ Passed

- Advice** REAR BRAKE PADS WORN

MOT #14

2016-08-04 12:26

MOT test number

439162452808

Result

✓ Passed

**MOT #13** 2015-08-03 14:13**MOT test number** 377955615471**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2014-10-18 16:59**MOT test number** 825401394286**Result** ✗ Failed**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Rear Sub-frame corroded and seriously weakened (2.4.G.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-08-06 14:32**MOT test number** 317688014206**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f tyre smooth on inside edge**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2013-10-19 15:20**MOT test number** 327592393407**Result** ✓ Passed

**MOT #9** 2012-10-26 09:04**MOT test number** 868200602314**Result** ✓ Passed**Notice** Front n/s and o/s tyres wear on edges**Notice** Front o/s tyre cut in tread no cord showing**MOT #8** 2012-10-20 10:59**MOT test number** 697064392299**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/f tyre has cut in tread. no cord showing**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2011-10-19 10:28**MOT test number** 335122091286**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres worn on edges**MOT #6** 2010-10-20 13:04**MOT test number** 702603790264**Result** ✓ Passed**MOT #5** 2009-10-29 11:40**MOT test number** 953172109308**Result** ✓ Passed

**MOT #4** 2009-10-26 11:54**MOT test number** 370789099408**Result** ✗ Failed**Advice** Offside Inner Rear brake disc slightly pitted (3.5.1h)**Fail** Nearside Inner Front brake disc excessively pitted (3.5.1h)**Advice** Nearside Inner Rear brake disc slightly pitted (3.5.1h)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Inner Front brake disc slightly pitted (3.5.1h)**MOT #3** 2008-10-20 18:10**MOT test number** 341394798482**Result** ✓ Passed**MOT #2** 2007-10-22 11:58**MOT test number** 674265497242**Result** ✗ Failed**Pass with rectification** Centre Front registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Centre Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #1** 2007-10-22 11:58**MOT test number** 713095197228**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
5 August 2023

✕
MOT

Expired:
12 April 2024

Tax status	Expired at 5 August 2023
Days left	269 days too late
MOT expiry date	12 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-10-15
Last registration	2023-04-13
Complete history	See info



Registration #1	2004-10-15	23 mi
Registration #2	2007-10-22	16.519 mi
Registration #3	2008-10-20	20.591 mi
Registration #4	2009-10-26	23.026 mi
Registration #5	2009-10-29	23.053 mi
Registration #6	2010-10-20	26.968 mi
Registration #7	2011-10-19	31.610 mi
Registration #8	2012-10-20	35.791 mi
Registration #9	2012-10-26	35.856 mi
Registration #10	2013-10-19	41.630 mi
Registration #11	2014-08-06	46.082 mi
Registration #12	2015-08-06	51.277 mi
Registration #13	2016-08-06	56.472 mi
Registration #14	2017-08-06	61.667 mi
Registration #15	2018-08-06	66.862 mi
Registration #16	2019-08-06	72.057 mi
Registration #17	2020-08-06	77.252 mi
Registration #18	2021-08-06	82.447 mi
Registration #19	2022-08-06	87.642 mi
Registration #20	2023-04-13	92.837 mi
Registration #21	2023-04-13	92.837 mi
Registration #22	2023-04-13	92.837 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1534 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	161051