





report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 L
Colour	Black
Year of manufacture	2006
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-24

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



KF06HSY report date: 2024-03-29

MOT history

MOT expiry date	2024-08-08
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #20	2023-07-31 10:26
MOT test number	371102776374
Result	✓ Passed
Next expiry date	2024-08-08

MOT #	#19	2023-07-29 09:59
MOT t	test number	449410875417
Resul	t	🗙 Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively Both front blades to	orn (3.4 (b) (ii))
Adv	ice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #18		2022-08-05 10:41
MOT test	number	974032477847
Result		✓ Passed
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to legal limit/worn on edge outside edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



MOT #17

Result

KF06HSY report date: 2024-03-29

2021-08-09 11:39

X Failed

MOT test number 619641703830

Advice Nearside Play in steering rack inner joint(s)

MOT #16 2021-08-06 16:22

MOT test number 898737289829

Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Power steering pump has slight seepage (2.1.5 (a))

Advice Nearside Play in steering rack inner joint(s)

MOT #15 2020-10-01 14:54

MOT test number 602563352646

Result
✓ Passed

Advice Both Front steering rack arms have slight play on the inner joints

MOT #14 2020-10-01 12:01

MOT test number 620065024160

Result X Failed

Advice Both Front steering rack arms have slight play on the inner joints

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #13		2019-09-25 15:12
MOT test	number	341289917503
Result		✓ Passed
Advice	Nearside Rear tyres cracking	
Advice	Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i)))
Advice	Offside Rear tyres cracking	
Advice	Offside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	

MOT #12	2018-10-05 09:58
MOT test number	944554836956
Result	✓ Passed
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #11	2017-10-05 10:58
MOT test number	316971283741
Result	✓ Passed
MOT #10	2016-09-30 10:24
MOT test number	143862690580
Result	✓ Passed
Advice Both front tyres wearing on edges	

MOT #9	2015-10-08 11:04
MOT test number	575809045735
Result	✓ Passed
MOT #8	2014-10-13 10:53
MOT test number	759246484205
Result	√ Passed

CarCheck.co.uk page 5/13



MOT #7

MOT #3

Result

MOT test number

MOT test number

KF06HSY

report date: 2024-03-29

2013-10-14 12:24

2011-02-15 13:46 108506341055

330226040066

✓ Passed

		2013 10 11 12121
MOT test	number	786067683223
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #6		2013-05-29 13:58
MOT test	number	809239543159
Result		✓ Passed
MOT #5		2013-02-11 14:07
MOT test	number	729822843041
Result		✓ Passed
MOT #4		2012-02-14 14:38
MOT test	number	796465842029
Result		✓ Passed

MOT #2	2010-02-15 10:42

Result

Passed

MOT #1	2009-02-11 09:30
MOT test number	883272949046
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

O		1-1-4	
- 1114	vner	піст	$\alpha r v$
\cup	VIICI	IIIJU	ע וט.

e when moterly	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



KF06HSY report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 11/13



KF06HSY report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-10
Last registration	2023-07-31
Complete history	See info



Registration #1	2006-03-10	29 mi
Registration #2	2009-02-11	9.548 mi
Registration #3	2010-02-15	11.629 mi
Registration #4	2011-02-15	13.798 mi
Registration #5	2012-02-14	15.327 mi
Registration #6	2013-02-11	18.269 mi
Registration #7	2013-05-29	18.943 mi
Registration #8	2013-10-14	23.463 mi
Registration #9	2014-10-13	30.169 mi
Registration #10	2015-10-08	33.085 mi
Registration #11	2016-09-30	36.200 mi
Registration #12		77.777 440
Registration #13		77.777 466
Registration #14		77.777 440
Registration #15		77.777 466
Registration #16		77.777 460
Registration #17		77,777 ess
Registration #18		77.777 460
Registration #19		71.777 es
Registration #20		11.177 es
Registration #21		77,777 46
Registration #22		11.177 ea

More info >

CarCheck.co.uk page 12/13



KF06HSY report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1426 mm
Length	3835 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	NOT KNOWN

CarCheck.co.uk page 13/13