



HONDA



LCIOJUF


report date: 2024-03-29

General information

Make	HONDA
Model	INSIGHT IMA SE
Colour	Black
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	121 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-07
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	33
Total items failed	7

MOT #15	2023-09-20 14:04
---------	------------------

MOT test number	729739911138
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-06
------------------	------------

- Minor

Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Front Vehicle structure is deformed but structural rigidity is not significantly reduced crossmember (6.1.1 (a) (i))
- Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge worn edges (5.2.3 (e))
- Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Minor

Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #14**

2023-09-20 09:57

MOT test number

448101099200

Result**✗ Failed**

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn edges (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Front Vehicle structure is deformed but structural rigidity is not significantly reduced crossmember (6.1.1 (a) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #13

2022-10-03 08:54

MOT test number

322788470320

Result**✓ Passed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

**MOT #12**

2022-10-03 08:54

MOT test number

777742578943

Result**✗ Failed****Advice**

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11

2021-10-07 15:28

MOT test number

239246945105

Result**✓ Passed****MOT #10**

2021-10-06 14:27

MOT test number

923493734174

Result**✗ Failed****Fail**

Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail

Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail

Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #9

2020-09-30 09:38

MOT test number

992204681085

Result**✓ Passed****Advice**

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2019-09-17 10:33**MOT test number** 798544852918**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-09-18 14:18**MOT test number** 897450886074**Result** ✓ Passed**MOT #6** 2017-10-12 08:27**MOT test number** 237150345499**Result** ✓ Passed

- Advice** Brake pedal rubber worn
- Advice** Rear wiper blade split
- Advice** Crack in the nsf indicator lense
- Advice** Osf seat belt slow at retracting
- Advice** Nsf tyre worn outer edge

MOT #5 2016-11-02 09:21**MOT test number** 504080803310**Result** ✓ Passed

**MOT #4** 2015-10-21 09:35**MOT test number** 723414361560**Result** ✓ Passed**MOT #3** 2014-10-20 09:31**MOT test number** 377923194232**Result** ✓ Passed**Notice** Brake pedal rubber wearing through**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre worn 3mm**MOT #2** 2013-11-04 14:26**MOT test number** 797778803343**Result** ✓ Passed**MOT #1** 2013-05-10 13:52**MOT test number** 998690033119**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-13
Last registration	2023-09-20
Complete history	See info



Registration #1	2010-05-13	22 mi
Registration #2	2013-05-10	15.803 mi
Registration #3	2013-11-04	18.139 mi
Registration #4	2014-10-20	24.775 mi
Registration #5	2015-10-21	32.302 mi
Registration #6	2016-11-02	41.085 mi
Registration #7	2017-10-12	54.685 mi
Registration #8	2018-09-18	67.309 mi
Registration #9	2019-09-17	88.665 mi
Registration #10	2020-09-17	100.000 mi
Registration #11	2021-09-17	111.335 mi
Registration #12	2022-09-17	122.670 mi
Registration #13	2023-09-17	134.005 mi
Registration #14	2024-09-17	145.340 mi
Registration #15	2025-09-17	156.675 mi
Registration #16	2026-09-17	168.010 mi
Registration #17	2027-09-17	179.345 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1028716