



PX6IGKJ

report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 110
Colour	Red
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	119 g/km
CO2 label	C





## Internet history

### Entry 4

Date	2023-12-21
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

### Entry 3

Date	2023-12-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

### Entry 2


Date	2023-11-15
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 1

Date	2021-10-10
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-08-30
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #14	2023-08-08 14:39
MOT test number	262836346529
Result	✓ Passed
Next expiry date	2024-08-30

MOT #13	2023-08-02 11:14
MOT test number	640115062427
Result	✗ Failed
Fail	Offside Reversing lamp inoperative (4.6.1 (a))
Advice	Grease leak from nearside outer drive shaft gaiter
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #12	2022-08-31 09:11
MOT test number	502396710159
Result	✓ Passed

MOT #11	2021-10-19 07:43
MOT test number	726391631475
Result	✓ Passed

**MOT #10**

2021-10-18 15:08

**MOT test number**

310090712737

**Result****✗ Failed****Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Horn not working (7.7 (a))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2020-11-05 13:32

**MOT test number**

644847188886

**Result****✓ Passed****Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement wishbone (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8**

2019-11-27 16:27

**MOT test number**

479690037670

**Result****✓ Passed****MOT #7**

2019-11-27 10:34

**MOT test number**

113375751339

**Result****✗ Failed****Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2018-11-30 14:27**MOT test number** 860740316672**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-11-30 10:49**MOT test number** 822465960819**Result** ✗ Failed**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2017-12-02 13:16**MOT test number** 536673408268**Result** ✓ Passed**MOT #3** 2016-11-25 10:59**MOT test number** 941620570664**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)



MOT #2	2015-11-30 16:04
MOT test number	865325910250
Result	✓ Passed
Advice	Child seats fitted not allowing full inspection of adult seat belts

MOT #1	2014-10-31 11:50
MOT test number	309974304317
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-29
Current registration	 XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-03
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2011-12-03	23 mi
Registration #2	2014-10-31	26.467 mi
Registration #3	2015-11-30	30.819 mi
Registration #4	2016-11-25	33.436 mi
Registration #5	2017-12-02	38.213 mi
Registration #6	2018-11-30	40.786 mi
Registration #7	2018-11-30	40.786 mi
Registration #8	2019-11-27	44.021 mi
Registration #9	2019-11-27	44.021 mi
Registration #10	2020-11-05	46.547 mi
Registration #11	2020-11-05	46.547 mi
Registration #12	2020-11-05	46.547 mi
Registration #13	2020-11-05	46.547 mi
Registration #14	2020-11-05	46.547 mi
Registration #15	2020-11-05	46.547 mi
Registration #16	2020-11-05	46.547 mi
Registration #17	2020-11-05	46.547 mi
Registration #18	2020-11-05	46.547 mi
Registration #19	2020-11-05	46.547 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1413 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	8D32195
---------------	---------