





report date: 2024-03-28

#### General information

Make	FORD	
Model	TRANSIT CUSTOM 300 BASE P/V L1 H1	
Colour	White	
Year of manufacture	2018	
Top speed	103 mph	
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	96 kW / 131 HP / 104 BHP
Max. torque	360 Nm
<b>Engine capacity</b>	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-11-05

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



ML18UEZ report date: 2024-03-28

MOT history

MOT expiry date	2024-11-08
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	6

MOT #5	2023-11-09 13:56
MOT test number	290710252477
Result	✓ Passed
Next expiry date 2024-11-08	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2023-11-09 10:01
MOT test number	611986754739
Result	<b>X</b> Failed
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2022-10-04 10:01
MOT test number	394160320192
Result	✓ Passed
Advice Front Brake pad(s) wearing thi	n (1.1.13 (a) (ii))
Minor Nearside Front Windscreen dam	naged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #2** 2022-10-03 11:15 375725873823 **MOT** test number Result × Failed Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Front Registration plate does not conform to the specified requirements (0.1 (d)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Rear Registration plate does not conform to the specified requirements (0.1 (d)) Fail

MOT #1

MOT test number

415583450403

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manners and the same of the sa	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



ML18UEZ report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-05-11
Last registration	2023-11-09
Complete history	See info



Registration #1	2018-05-11	21 mi
Registration #2	2021-06-02	43.166 mi
Registration #3		11.177 es
Registration #4	2022-10-03	54.603 mi
Registration #5		11.777 mi
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



## Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2 mm
Kerb weight	1815 kg
Max. allowed weight	3000 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	3 page 11/1

Number of axles 2
Engine number JY11961