



report date: 2024-03-28

General information

| | |
|---------------------|--------|
| Make | NISSAN |
| Model | TIIDA |
| Colour | Black |
| Year of manufacture | 2010 |
| Gearbox | - |

Engine & fuel consumption

| | |
|-----------------|----------|
| Engine capacity | 1.598 cc |
| Fuel type | Petrol |
| CO2 emission | 165 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-25 |
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #16 | 2024-02-14 09:58 |
| MOT test number | 765933618716 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-25 |

| | |
|-----------------|------------------|
| MOT #15 | 2023-02-08 16:04 |
| MOT test number | 671857583257 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #14 | 2022-02-02 10:53 |
| MOT test number | 168507046670 |
| Result | ✓ Passed |

Advice Both front tyres cracking in tread pattern

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

| | |
|-----------------|------------------|
| MOT #13 | 2021-02-26 17:16 |
| MOT test number | 712232879863 |
| Result | ✓ Passed |

**MOT #12** 2021-02-26 17:16**MOT test number** 916929304517**Result** ✗ Failed**Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**MOT #11** 2019-12-20 11:29**MOT test number** 839424685858**Result** ✓ Passed**MOT #10** 2019-12-17 16:37**MOT test number** 494139091116**Result** ✗ Failed**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2019-03-14 15:49**MOT test number** 524137598044**Result** ✓ Passed**MOT #8** 2018-03-21 15:49**MOT test number** 813355770227**Result** ✓ Passed**MOT #7** 2017-02-24 15:24**MOT test number** 274093990841**Result** ✓ Passed

**MOT #6**

2016-03-14 11:15

MOT test number

595379840398

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5

2016-03-14 11:14

MOT test number

901236999925

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)

MOT #4

2014-12-19 11:41

MOT test number

145803754386

Result

✓ Passed

- Notice** Rear brake pads look worn
- Notice** Rear tyres wearing on edges
- Notice** Sill skirts fitted , cannot inspect outer sills

**MOT #3** 2014-12-16 15:47**MOT test number** 298020554326**Result** ✗ Failed**Notice** Rear tyres wearing on edges**Notice** Sill skirts fitted , cannot inspect outer sills**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Rear brake pads look worn**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #2** 2013-12-13 10:22**MOT test number** 955897743379**Result** ✓ Passed**MOT #1** 2013-03-07 17:41**MOT test number** 605266063080**Result** ✓ Passed**Advice** Offside Front Sub-frame synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 25 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |   |
| Plate since | 2024-03-28 |
| Current registration |   |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2010-03-12 |
| Last registration | 2024-02-14 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-03-12 | 28 mi |
| Registration #2 | 2013-03-07 | 21.705 mi |
| Registration #3 | 2013-12-13 | 28.061 mi |
| Registration #4 | 2014-12-16 | 36.737 mi |
| Registration #5 | 2014-12-19 | 36.785 mi |
| Registration #6 | 2016-03-14 | 42.672 mi |
| Registration #7 | 2016-03-14 | 42.672 mi |
| Registration #8 | 2017-02-24 | 46.007 mi |
| Registration #9 | 2018-03-21 | 49.038 mi |
| Registration #10 | 2019-03-21 | 51.377 mi |
| Registration #11 | 2019-03-21 | 51.377 mi |
| Registration #12 | 2019-03-21 | 51.377 mi |
| Registration #13 | 2019-03-21 | 51.377 mi |
| Registration #14 | 2019-03-21 | 51.377 mi |
| Registration #15 | 2019-03-21 | 51.377 mi |
| Registration #16 | 2019-03-21 | 51.377 mi |
| Registration #17 | 2019-03-21 | 51.377 mi |
| Registration #18 | 2019-03-21 | 51.377 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

| | |
|-----------------|--------|
| Number of seats | 5 |
| Engine number | 374989 |