



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-05
Pictures	47
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	45
Total items failed	1

MOT #12	2023-08-15 12:46
---------	------------------

MOT test number	676856858245
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-22
------------------	------------

- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Spare tyre defective
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Parking brake lever has little reserve travel
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2023-08-15 12:45

**MOT test number**

237423301676

**Result****✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Parking brake lever has little reserve travel
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Spare tyre defective
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2022-08-23 08:56

**MOT test number**

790418718290

**Result**

✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Inner faces (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9**

2021-06-30 15:41

**MOT test number**

925379523427

**Result**

✓ Passed

**MOT #8**

2021-06-29 08:44

**MOT test number**

506645736053

**Result**

✗ Failed

- MAJOR** Brake performance not tested (1.2.1 (g))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

**MOT #7** 2020-07-01 14:19**MOT test number** 757969359039**Result** ✓ Passed**MOT #6** 2019-06-21 13:53**MOT test number** 477101359304**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #5** 2018-06-26 11:14**MOT test number** 850346100645**Result** ✓ Passed**MOT #4** 2017-08-24 09:09**MOT test number** 421629016720**Result** ✓ Passed**Advice** Slight lip and corrosion on front brake discs**MOT #3** 2016-09-12 14:49**MOT test number** 382764805553**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened discs worn and slight pitting (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin outer pad 95% worn (3.5.1g)**MOT #2** 2015-09-08 09:47**MOT test number** 316550999809**Result** ✓ Passed



MOT #1	2014-09-19 16:35
MOT test number	385552464222
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
22 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	22 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SK61WVZ
Plate since	2019-09-29
Current registration	SK61WVZ
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-16
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2011-09-16	6 mi
Registration #2	2014-09-19	29.684 mi
Registration #3	2015-09-08	45.002 mi
Registration #4	2016-09-12	54.504 mi
Registration #5	2017-08-24	64.120 mi
Registration #6	2018-06-26	71.405 mi
Registration #7	2019-06-21	76.285 mi
Registration #8	2020-06-21	76.285 mi
Registration #9	2021-06-21	76.285 mi
Registration #10	2022-06-21	76.285 mi
Registration #11	2023-06-21	76.285 mi
Registration #12	2024-06-21	76.285 mi
Registration #13	2025-06-21	76.285 mi
Registration #14	2026-06-21	76.285 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBBH023291