



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI DSG DPF
Colour	Silver
Year of manufacture	2008
Top speed	128 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-31
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-05
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	32
Total items failed	15

MOT #18	2022-10-06 12:19
MOT test number	672501000199
Result	✓ Passed
Next expiry date	2023-10-05

MOT #17	2022-10-06 11:07
MOT test number	549692203668
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge serverly scrubbed and nearing chord level (5.2.3 (e))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #16**

2021-07-17 07:32

MOT test number

878175860925

Result

✓ Passed

- Advice** Both front tyres wearing on inner edges
- Advice** Covers fitted obstructing view
- Advice** Corrosion on body & underneath
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #15

2021-07-16 16:15

MOT test number

337552996685

Result

✗ Failed

- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Both front tyres wearing on inner edges
- Fail** Nearside Front Electrical wiring connectors for braking disconnected (4.11 (a) (iii))
- Advice** Covers fitted obstructing view
- Advice** Brake pad waring light on
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Corrosion on body & underneath

MOT #14

2020-10-20 12:09

MOT test number

308835570591

Result

✓ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13** 2019-04-12 10:45**MOT test number** 756311542260**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))**MOT #12** 2018-04-25 14:28**MOT test number** 266346092327**Result** ✓ Passed**MOT #11** 2018-04-24 08:19**MOT test number** 350074887507**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)**MOT #10** 2017-04-10 11:55**MOT test number** 702866114795**Result** ✓ Passed**Advice** Undertrays fitted obscuring some components

**MOT #9**

2017-04-10 09:08

MOT test number

572688530990

Result

✗ Failed

Advice Undertrays fitted obscuring some components**Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8**

2016-03-31 07:15

MOT test number

487932037294

Result

✓ Passed

Advice Offside Rear rear brake fluctuating, but not excessively brake disc slightly corroded (3.7.B.3)**Advice** Offside Rear Tyre worn close to the legal limit inner shoulder devoid of tread(advice replacement) (4.1.E.1)**Advice** Low brake pad light on but all pads appear okay**Advice** Nearside Rear rear brake fluctuating, but not excessively brake disc slightly corroded (3.7.B.3)**Advice** Nearside Rear Tyre worn close to the legal limit inner shoulder devoid of tread(advice replacement) (4.1.E.1)**Advice** Undertrays fitted obscuring some components**MOT #7**

2015-04-02 11:31

MOT test number

266212695069

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**MOT #6**

2014-04-15 15:13

MOT test number

935315904168

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components

**MOT #5** 2014-04-11 10:39**MOT test number** 286421804449**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** The low brake pad warning light is on but all brake pads appear okay**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-04-17 16:23**MOT test number** 537827503150**Result** ✓ Passed**MOT #3** 2013-04-17 10:57**MOT test number** 386757703130**Result** ✗ Failed**Fail** Nearside Front front brake juddering severely (3.7.A.2b)**Fail** Nearside rear brake juddering severely (3.7.A.5b)**Fail** Offside front brake juddering severely (3.7.A.2b)**Fail** Rear brake application uneven (3.7.B.2)**MOT #2** 2012-04-02 14:34**MOT test number** 355483992053**Result** ✓ Passed**Advice** Offside front brake juddering slightly (3.7.A.2b)**Advice** Nearside front brake juddering slightly (3.7.A.2b)**Notice** Under-trays fitted obscuring some underside components



MOT #1	2011-04-26 13:40
MOT test number	799946511131
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 November 2023

X

MOT

Expired:
5 October 2023

Tax status	Expired at 1 November 2023
Days left	179 days too late
MOT expiry date	5 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	NU08UZP
Plate since	2019-03-28
Current registration	NU08UZP
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-18
Last registration	2022-10-06
Complete history	See info



Registration #1	2008-04-18	15 mi
Registration #2	2011-04-26	34.783 mi
Registration #3	2012-04-02	45.243 mi
Registration #4	2013-04-17	56.745 mi
Registration #5	2013-04-17	56.745 mi
Registration #6	2014-04-11	68.169 mi
Registration #7	2014-04-15	68.207 mi
Registration #8	2015-04-02	77.645 mi
Registration #9	2016-03-31	86.922 mi
Registration #10	2017-04-10	96.812 mi
Registration #11	2018-04-10	106.702 mi
Registration #12	2019-04-10	116.592 mi
Registration #13	2020-04-10	126.482 mi
Registration #14	2021-04-10	136.372 mi
Registration #15	2022-04-10	146.262 mi
Registration #16	2023-04-10	156.152 mi
Registration #17	2024-04-10	166.042 mi
Registration #18	2025-04-10	175.932 mi
Registration #19	2026-04-10	185.822 mi
Registration #20	2027-04-10	195.712 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1671 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKP 284781