





report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	White
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-05-24
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	3

MOT #14	2023-05-25 08:00
MOT test number	216594262764
Result	✓ Passed
Next expiry date	2024-05-24

MOT #13	2022-05-20 14:50
MOT test number	399220895449
Result	✓ Passed

MOT #12	2021-05-21 10:55
MOT test number	400756813622
Result	✓ Passed

MOT #11	2021-05-21 10:55
MOT test number	401413902303

Result X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/13



MOT #10

RE11TXO report date: 2024-03-29

2019-11-14 16:36

MOT test number 732550081342

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Wheel arch liner not fully secured.

Advice Front exhaust joint weakened.

MOT #9 2019-11-14 15:48

MOT test number 714339914339

Result X Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Tyre worn close to legal limit. (5.2.3 (d) (i))

Advice Nearside Front Wheel arch liner not fully secured.

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front exhaust joint weakened.

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8 2018-11-23 11:24

MOT test number 364454929332

Result \(\sqrt{Passed} \)

Advice Exhaust flexi weakened

MOT #7 2017-11-03 13:37

MOT test number 882194046756

Result
✓ Passed

Advice Rear boot only opens by key

CarCheck.co.uk page 4/13



RE11TXO

report date: 2024-03-29

MOT #6 2016-11-16 14:39

MOT test number 286675004576

Result ✓ Passed

MOT #5 2015-11-24 12:31

MOT test number 340074424903

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2015-11-24 12:31

MOT test number 833677612245

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #3 2014-12-03 13:25

MOT test number 196387834302

Result

Passed

MOT #2 2014-05-27 11:07

MOT test number 478677644157

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 5/13



MOT #1 2014-05-27 11:07

MOT test number 259807644177

Result

X Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-31
Last registration	2023-05-25
Complete history	See info



Registration #1	2011-05-31	17 mi
Registration #2	2014-05-27	19.897 mi
Registration #3	2014-12-03	23.512 mi
Registration #4	2015-11-24	35.834 mi
Registration #5	2015-11-24	35.834 mi
Registration #6	2016-11-16	50.811 mi
Registration #7	2017-11-03	69.661 mi
Registration #8	2018-11-23	89.208 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine numberB560J085