



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	LUPO SE
Colour	Black
Year of manufacture	2002
Top speed	94 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	50 BHP
Max. torque	86 Nm at 3.600 rpm
Engine capacity	999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-01-31
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	44
Total items failed	8

MOT #27 2024-02-01 11:18

MOT test number 601005690137

Result ✓ Passed

Next expiry date 2025-01-31

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #26 2024-01-26 12:14

MOT test number 369619252353

Result ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Tyre has had the tread recut (5.2.3 (g))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Stop lamp(s) not working center light (4.3.1 (a) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MAJOR** Emissions unable to be completed Exhaust leaking (8.2.2.2 (e))

**MOT #25** 2022-09-20 14:56**MOT test number** 667014229379**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #24** 2022-09-06 13:10**MOT test number** 503815594879**Result** ✗ Failed**DANGEROUS** Central Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #23** 2021-09-09 10:37**MOT test number** 507682388609**Result** ✓ Passed**Advice** Rear beam bushes worn**MOT #22** 2021-08-31 10:06**MOT test number** 521095134804**Result** ✗ Failed**MAJOR** Offside Headlamp insecure (4.1.1 (c))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**MOT #21** 2020-09-02 09:37**MOT test number** 894522014315**Result** Passed**MOT #20** 2020-07-30 11:39**MOT test number** 410573250993**Result** Failed

- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- MAJOR** Nearside Rear Shock absorbers damaged to the extent that it does not function (5.3.2 (b))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #19 2020-02-21 09:16**MOT test number** 836780348559**Result** Failed

- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- DANGEROUS** Offside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #18 2019-08-20 17:14**MOT test number** 375881941969**Result** Passed**MOT #17** 2018-08-14 15:48**MOT test number** 725217267560**Result** Passed

**MOT #16** 2017-08-07 10:49**MOT test number** 323579154186**Result** ✓ Passed**MOT #15** 2016-08-16 09:29**MOT test number** 179675580477**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Oil leak**MOT #14** 2016-08-16 09:29**MOT test number** 635157209303**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Oil leak**MOT #13** 2015-08-20 10:33**MOT test number** 285602235296**Result** ✓ Passed**Advice** Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #12** 2014-08-13 14:49**MOT test number** 167775024272**Result** ✓ Passed**Advice** Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #11** 2013-08-16 15:29**MOT test number** 866998323273**Result** ✓ Passed**Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2013-08-16 10:30**MOT test number** 237188523281**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Lower coil spring broken (2.4.C.1a)**Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Brake hose leaking (3.6.A.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2012-08-13 10:01**MOT test number** 117716522228**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #8** 2012-08-13 10:01**MOT test number** 599916522213**Result** ✓ Passed

**MOT #7** 2011-09-30 12:45**MOT test number** 865283171245**Result** ✓ Passed**MOT #6** 2010-03-23 15:55**MOT test number** 180042480405**Result** ✗ Failed**Pass with rectification** Offside Front Brake pad(s) insecure (3.5.1g)**MOT #5** 2010-03-23 15:55**MOT test number** 472102080004**Result** ✓ Passed**MOT #4** 2008-08-13 09:44**MOT test number** 460666728254**Result** ✓ Passed**MOT #3** 2007-08-15 09:18**MOT test number** 962597627298**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** NO A.B.S. FITTED**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2006-08-23 13:20**MOT test number** 400095436207**Result** ✓ Passed



MOT #1	2005-12-15 14:50
MOT test number	964969045387
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ND52WEU
Plate since	2024-03-28
Current registration	 ND52WEU
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-11-28
Last registration	2024-02-01
Complete history	See info



Registration #1	2002-11-28	10 mi
Registration #2	2005-12-15	11.967 mi
Registration #3	2006-08-23	15.531 mi
Registration #4	2007-08-15	23.218 mi
Registration #5	2008-08-13	34.374 mi
Registration #6	2010-03-23	43.462 mi
Registration #7	2011-09-30	48.881 mi
Registration #8	2012-08-13	50.962 mi
Registration #9	2013-08-16	51.368 mi
Registration #10	2013-08-16	51.368 mi
Registration #11	2014-08-13	53.438 mi
Registration #12	2015-08-20	53.635 mi
Registration #13	2016-08-16	57.362 mi
Registration #14	2016-08-16	57.362 mi
Registration #15	2016-08-16	57.362 mi
Registration #16	2016-08-16	57.362 mi
Registration #17	2016-08-16	57.362 mi
Registration #18	2016-08-16	57.362 mi
Registration #19	2016-08-16	57.362 mi
Registration #20	2016-08-16	57.362 mi
Registration #21	2016-08-16	57.362 mi
Registration #22	2016-08-16	57.362 mi
Registration #23	2016-08-16	57.362 mi
Registration #24	2016-08-16	57.362 mi
Registration #25	2016-08-16	57.362 mi
Registration #26	2016-08-16	57.362 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1459 mm
Length	3527 mm
Wheel base	2321 mm
Kerb weight	946 kg

Additional information

Fuel tank capacity	34 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AUC233163